

TOWNSHIP 27½ RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12863)

Point for the cor. of secs. 32 and 33 only, on the S. bdy. of T27½S R8W.

Set an iron post 28" long, 2½" dia., 22" in the ground, and in a mound of stone 2 ft. base, to top, with brass cap mkd.

T 27½ S | R 8 W
 S 32 | S 33
 S 5
T 28 S R 8 W
1961

from which

A Hemlock 27" dia., bears N.73°E., 48 lks. dist. mkd. T27½S R8W S33 BT.

A Hemlock 18" dia., bears N.22½°W., 101 lks. dist. mkd. T27½S R8W S32 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 15, 1970 - C.S. File 54/113-12

Found - Only shattered remains of one BT as follows: 18" Hemlock N.22½°W., 66.7 ft., dead, shattered stump, fragmentary scribe on portion of blaze.

No trace of NE. BT or 1961 brass cap at corner point.

Set Brass cap at cor. mkd: County Surveyors Office

T27½S
S 32 | S 33 R8W
T 28 S
1970

New BT - 30" Hemlock N.4°W., 112.4 ft. mkd. "T27½S R8W S32 CS BT". This is only suitable tree close.

Corner was destroyed by large rocks rolling down from new Burnt Mt. access road construction and lies on very steep, NE. slope. The standard cor. of secs. 4 & 5, T28-8 is 42.9 ft. S.88°E.