

TOWNSHIP 27½ RANGE 08 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION C C for Secs. 32 and 33 only (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12872)

Point for the closing corner of secs. 32 and 33.
Set an iron post 28" long, 2½" dia., 22" in the ground with brass cap mkd. T 27 S R 8 W

S 33

S 32 | S 33
T 27½ S | R 8 W
C C
1961

from which

- A Hemlock 16" dia., bears S.34°E., 58 lks. dist. mkd. T27½S R8W S33 CC BT.
- A Cedar 16" dia., bears S.43½°W., 129 lks. dist. mkd. T27½S R8W S32 CC BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
May 14, 1970 - C.S. File 54/113-9

Found 1961 Cadastral brass cap, out of position and buried.
RESET BRASS CAP at corner point from 1961 BTs as follows:

- Orig. 16" now 17" Hemlock, alive, S.34°E., 38.3 ft. scribe visible on unhealed blaze.
- Orig. 16" now 16" Cedar, dead, S.43½°W., 85.1 ft. scribe visible on unhealed blaze.

New BT:

10" Hemlock S.85°W., 22.1 ft. mkd. T27½S R8W S32 CC CS BT.
Corner falls on West tract of cat skid trail and 91 ft. N. and 95 ft. E. of Wilson Creek, course N.W.

Tony Hostetter - For: Weyerhaeuser - Feb. 2005 (added 7/31/2019) - M147-36

Found - 1961 BLM brass cap from which:
18" Hemlock stump, WEYCO tag, scribing visible, bears S.34°E., 38.3 ft.
12" Hemlock stump, WEYCO tag, scribing visible, bears S.85°W., 22.1 ft.
New BTs- 12" Fir, scribed "S33 CC BT", bears N.73°19'E., 10.4 ft. to spike.
10" Fir, scribed "S32 CC BT", bears S.02°15'E., 2.8 ft. to spike.

continued next page

TOWNSHIP 27½ RANGE 08 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION C C for Secs. 32 and 33 only (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - Nov. 7, 2018 (Filed 11/17/2021) - C.S. File 67/50-2

T Hostetter notes that the monument is set 6.18 ft. north of record position per M 147-36 in 2005, apparently based on his measured bearing vs. the 1961 record bearing to the USBLM brass cap 8.23 chains west. This corner renewal finds that the position of the found monument which was restored from the original 1961 bearing trees by V. Tracy, DCSO, in 1970 per C.S. File 54/113-9 matches the 1961 and 1970 records to the found bearing trees Therefore, I accept the monument as the original 1961 corner position.

Found - A 2½" o.d. iron pipe as reset by V. Tracy, DCSO in 1970 firmly set, projecting 5" above the ground with a ¾" brass cap (properly) marked

BTs by White, Jelley and Jelley in 1961 -

A 18"x5' tall metal capped hemlock stump bears S.34°E., 38.2 ft

A 9"x4' tall broken cedar stump bears S.43½°W. 85.1 ft BT by Tracy, in 1970 -

A 12" metal capped hemlock stump bears S.85°W. 22.1 ft BTs by Hostetter in 2005

A 14" D.Fir bears N.73°19'E., 11.3 ft. (Rec. 10.4 ft. to a spike in the BT face).

A 11" D. Fir bears S.2°15'E., 3.6 ft. (Rec. 2.8 ft. to a spike in the BT face).

New - A 4" Cedar bears S.62°E., 15.8 ft. scribed "X", "CSBT"

A 8" D.Fir bears N.2°30'E., 13.2 ft. scribed "T27½S R8W S32 CS" "BT".

Note - All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to a 2½" PK nail in the side and center of the root crown.

Corner is located on a moderate west slope approximately 220 ft east of logging access road. Compass declination: 15°E.