

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5 only, T28-8

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5784)

 Marked a Hemlock 6" dia., for cor. secs. 5 and 4, from which
 A Hemlock 6" dia., bears S.48°W., 13 lks.
 A Hemlock 24" dia., bears S.88°E., 11 lks.

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12862)

 The standard cor. of secs. 4 and 5, perpetuated with an iron pipe, 2" dia., protruding 18" above ground with a metal tag, mkd. Bureau of Land Management, Approximate Corner Point 406, fastened to top from which original bearing trees:

A Hemlock 32" dia., bears S.81°E., 11 lks. dist., no marks remain. (Rec. brg. S.88°E.)

A Hemlock 10" dia., bears S.39°W., 13 lks. dist., mkd. with opened, rotted out face. The tree is hollow, (Rec. brg. S.45°W.)

The original corner tree, a Hemlock 10" dia., is lying downhill to the SE.; about 30 lks. dist., under a large Fir log, and is mkd. S5 on one open face and S4 on opposite open face. It is not possible to determine the exact point of origin of this tree.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap mkd:

S 5	S 4
T 28 S	R 8 W
S	C
1961	

from which

A Hemlock 12" dia., bears S.36°E., 76 lks. dist., mkd. T28S R8W S4 SC BT.

A Hemlock 24" dia., bears S.12°W., 40 lks. dist., mkd. T28S R8W S4 SC BT.

Deposit 2" Iron pipe alongside iron post.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 15, 1970 - C.S. File 54/113-13

 Found - 1961 BLM brass cap, in pipe, with 2" I.P. alongside. Orig. 32" Hemlock S.81°E., 7.3 ft., alive & tagged. 12" Hemlock, alive, S.36°E., 50.2 ft., tagged, blaze nearly healed. (Cont. Next Page)

TOWNSHIP 27½ RANGE 08 POINT IDENTIFIER # 301100

PRIMARY CORNER DESCRIPTION North Sec. Cor. for 4 & 5, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

All other BTs gone, due to large rocks and logs in fill of new Burnt Mt. access road.
New BT - 32" Hemlock S.1½°W., 63.5 ft. mkd. T28S R8W S5 SC CS BT.
Corner lies on very steep easterly slope about 125 ft. W. of Wilson Creek, course NW.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15590-91)

The standard cor., monumented with an iron post 2½" dia., firmly set projecting 4" above ground, with brass cap mkd. in 1961, from which the remains of the orig. bearing trees:

A root hole bears N.84½°E., 11 lks. dist., with a down Hemlock alongside 34" dia., no marks visible. (Rec. S.81°E.)

and the remains of bearing trees mkd. by White, etal

A Hemlock 14" dia., bears S.36°E., 76 lks. dist., with fragmentary scribe marks visible on open blaze.

A Hemlock stump 27" dia., bears S.15°W., 38 lks. dist., no marks visible. (Rec. S.12°W., 40 lks.)

and a bearing tree not of record

A Hemlock 32" dia., bears S.1°W., 99 lks. dist., with scribe marks 28S R8W S4 SC CS BT visible on open blaze.

ADD Marks 1975 to brass cap.

Fd. OK Dec. 1986 by R. Hintz - M 103-8