

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5468)

Set yew post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S19 on N & 30 on S face; from which
A hemlock, 8" dia., bears S.78°E., 8 lks., mkd: ¼ S30 BT.
A hemlock, 5" dia., bears N.5°E., 17 lks., mkd: ¼ S19 BT.

Bruce Shaner - For: Umpqua National Forest - May 13, 1968 - C.S. File 55/74

Orig. corner set by U. S. Gov't survey in 1909, and described as follows:

Set yew post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S19 on N & 30 on S face; from which

A hemlock, 8" dia., bears S.78°E., 8 lks., mkd: ¼ S30 BT.

A hemlock, 5" dia., bears N.5°E., 17 lks., mkd: ¼ S19 BT.

I found a badly decayed 4" square x 36" long Yew Post with scribe "4" and portions of other scribes visible; from which post a:

7" hemlock, orig. BT, badly chopped, no scribes visible, bears N.5°E, 11.2 ft.

8" hemlock, orig. BT, bearing S.78°E., 5.3 ft now missing.

The corner is at junction of very old blazed line running E-W and one running South. Original line calls of ravine at 3 chains E and ridge at 4 chains E are good.

At the location of the orig. corner post I placed a Brass Cap which I marked "T28S, R2W, ¼ S, S19 & S30, 1968, ORE 4906", and from which Brass Cap a

7" hemlock, orig. BT, badly chopped, no scribes visible, bears N.5°E, 11.2 ft.

44" D.Fir, I scribed "¼ S S19 T28S R2W BT, bears N.7°W, 18.0 ft.

10" Yew BT, I scribed "¼ S S30 T28S R2W BT", bears S.34°W. 24.5 ft.

Donald R. Stone - For: U.S. Forest Service - April 1977 (Ren. added 5/19/2009) - M 63-80

Found - Brass cap
12" Yew S.34°W., 24.5 ft. scribing visible.
New BT - 10" Hemlock bears N.84°W., 77.7' scribed "¼ S 19 BT" with brass washer, stamped "RLS 835" Attached

continued next page

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Leonard Herzstein, USFS & Deputy Co. Surveyors Office -
Witness: Jim Landrum - Nov. 18, 1981 - C.S. File 61/29-26

CONDITION REPORT ONLY

Found - 1½" Dia. I.P. firmly set projecting 14" above ground
with brass cap, properly mkd., set by Shaner in
1968.

I add 2 ft. dia. mound of stone with IP now
projecting 10".

12" yewood, bears S.34°W., 24.5 ft. with scribe
marks "¼ S30 T28S R2W BT" visible on partly
healed blaze.

44" D. Fir stump, bears N.7°W., 18.0 ft. with no
marks visible.

A 8" hemlock bears N.84°W., 77.7 ft. with scribe
marks "¼ S19 BT" and brass washer stamped "RLS
835" visible on partly healed double blaze. (Not
of record, 1977, Donald Stone RLS #835)

Note - Corner is 75 ft. west of USFS Rd. #2817 and about
180 ft. north of standing timber.