

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Pages 5451-2)</p> <p>-----</p> <p>Set fir post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S32 on W & 33 on E face; from which A fir, 9" dia., bears S.72°W., 20 lks., mkd: ¼ S32 BT. A fir, 10" dia., bears N.32°E., 4 lks., mkd: ¼ S33 BT.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy & Crew - May 18, 1968 - C.S. File 54/26-6</p> <p>-----</p> <p>Found - Orig 9" now 10" Fir S.72°W. 13.2 ft now badly rotted stump, shows "BT" scribe on unhealed blaze. Orig. 10" now 11" fir N.32°E., 2.6 ft. now down shows "S" & frag. scribe on unhealed face. Set brass cap at cor mkd: County Surveyors T28S ¼ S32 S33 R2W Office 1966 Brass cap set in ground in axe notch on N side of 30" log laying on cor. New BTs- 17" W.Fir N.31°E., 25.4 ft. mkd: ¼ S33 CS BT 7" W.Fir S.44°W., 31.3 ft. mkd: ¼ S32 CS BT</p>
<p>Brent Knapp - For: Umpqua Indian Forest Management, LLC - 9/2021 - M179-80</p> <p>-----</p> <p>Found - Brass cap Rotten stump remnant bears S.44°W., 31.3' 57" Fir (unrecorded) with tag from 1958, axe scars, no scribe, bears S.58°E., 29.04'</p> <p>Set - A 8" Fir scribed "¼ S33 BT" bears S.24°E., 8.5' A 10" Fir scribed "¼ S32 BT" bears S.65°W., 11.9' A 10" Fir scribed "¼ S32 BT" bears N.52°W., 19.0' A 12" Fir scribed "¼ S32 BT" bears S.57°W., 21.8'</p>
<p> </p>