

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 12 Page(s) 4962-63)

A point, 40.00 chs. E. of the closing cor. of secs. 1 & 2, Set an iron post, 3 ft. long, 1" dia., 27" in the ground for ¼ sec. cor. of sec. 1, only with brass cap mkd.

¼ S 1
1923

from which

A Fir 48" dia., bears S.26°E., 212 lks. dist. mkd. ¼ S1 BT.

A Fir 84" dia., bears S.43°W., 75 lks. dist. mkd. ¼ S1 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Oct. 1968 - C.S. File 54/40-85

Found - 1923 GLO brass cap under log and bent over.
Orig. 48" now 50" Fir, alive, S.26°E., 139.9 ft., blazed, no scribe visible.
Orig. 84" now 85" Fir, dead, S.43°W., 49.5 ft., open and find "¼ BT" scribe.

Reset brass cap at cor. point and remove portion of log.

New BTs- 80" D.Fir S.23°W., 43.0 ft. mkd. "¼ S1 CS BT"

15" R.Fir S.62°E., 116.6 ft. mkd. "¼ S1 CS BT"

Corner lies on northerly slope in dense vine maple thicket.