

PRIMARY CORNER DESCRIPTION North 1/4 Cor Sec 4 only, T29-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6326)

Set Dogwood post for ¼ sec. cor., from which
A Fir 5" dia., bears N.58°E., 6 lks.
A Maple 8" dia., bears S.12°W., 26 lks.

GLO resurvey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5561)

¼ sec. cor., which is a stake greatly decayed, marked as described by the surveyor general. Bearing trees have been destroyed. Set Fir stake 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. and S. 4 on S. face, and dig pits, 18 x 18 x 12 ins., E. and W. of cor., and raise mound of earth, 3½ ft. base, 1½ ft. high S. of cor., from which
A Maple 6" dia., bears S.80°E., 60 lks. dist. mkd. ¼ S4 BT
No other tree fit to mark.

Survey by Warren D. Hootman - For: Mr. J.P. Heath - Sept. 21, 1960 (Filed Jan. 13, 1961) C.S. File 51/164 and M 20-5

Find a Maple 12" DBH, which bears S.80°E., 39.6 ft. faced by no scribe marks left. The true corner point falls under a large log.
I set a 2" x 2" x 3 ft. stake on top of the log and witness as follows:
20" D.Fir DBH, bears N.67°30'E., 46.7 ft. mkd. BT S33.
Remark orig. 12" Maple DBH, bears S.80°E., 3.96 ft. mkd. BT ¼ S4 399.

Douglas Co. Surveyors Office - James Byron, Deputy - July 17, 1962 - C.S. File 52/126-6

Corner Report
Found BTs as recorded by Hootman, 1960 survey. I can find no evidence of old face or any indication that the Maple used to set cor. was the orig. BT. Also there is evidence, cut Fir stumps and standing trees, that suitable trees for BTs were in this area. I do not believe this cor. is as orig. set so do not renew it.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION North 1/4 Cor Sec 4 only, T29-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - R.B. Kimberling; P.L. Earle -
July 28, 1977 - C.S. File 59/38-9

Corner Report

Found - 2" x 2" x 34" cut (squared) stake with flagging,
stuck loosely in ground.

A 12" dia. Maple bears S.80°E., 39.6 ft. Appears too
small to have been 6" dia. in 1910. Orig. West
face split off, no evidence of orig. blaze.
Visible scribing in partially healed blaze (above
split off face).

A 17" dia. Maple bears East, 60 ± ft. of 12" Maple.
East side split out and center rotted away.
Healed scar indicates possible blaze facing
N.80°W., but no evidence of scribing.

From stake, a 20" now 24" D.Fir bears N.67½°E., 46.2
ft. with well healed blaze.

Survey by Bruce A. Shaner - For Longview Fibre - Sept. 25,
1978 - M 73-52

Set Brass cap mkd. ¼ S4 T29S R3W 1978, from which a
12" Maple, orig. BT, I rescribe bark, "1/4 S4 BT" bears
S.80°E., 39.6 ft.

10" Cedar, I scribe '1/4 S4 BT" bears S.53°W., 56.7 ft.

20" D.Fir, Hootman BT, stump bears N.67½°E., 46.7 ft.

Rob Ward - For: Seneca Jones Timber Co. - Jan. 2003 - M141-30

Found - 2-1/2" brass cap dated 1978

12" Maple bears S.80°E., 39.6' - open face

16" I.Cedar bears S.53°W 56.7' - healed face

20"x3' D.Fir stump bears N.67½°E., 46.7' no marks

New - 12" D.Fir bears S.6°E., 25.9' blazed Scribed "¼ S4
BT"