

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec Cor 6 & 7; 1 & 12, T28-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - James E. Freeman, under Contract #1 dated May 28, 1851 (DCSO records, Vol. 13 Page 5601)

Set post cor. of secs. 1, 6, 7, 12, from which
A B.Oak 18" dia., bears S.38°W., 20 lks. dist.
A B.Oak 12" dia., bears N.9°W., 20 lks. dist.
A B.Oak 12" dia., bears N.17½°E., 80 lks. dist.
A B.Oak 12" dia., bears S.33°E., 25 lks. dist.

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5609)

Set new post as per instructions. All bearing trees standing.

Doug. County Surveyors Office - James Byron, Deputy - M. Godfrey; S. Bilow - Nov. 1957 - C.S. File 49/21-19

Found - Orig. 18" now 30" B.Oak S.38°W., 13.2 ft., now down & partly rotted. I open & find reverse scribing BT.
Find stump holes for NE & NW original BTs.
Fence corner bears S.53°W., 6.0 ft.
Set brass cap at cor. mkd. S 1 | S 6 T28S County Surveyors
R5W S12 | S 7 R4W Office, 1957
New BTs -18" B.Oak bears S.77°E., 27.1 ft. scribed S7 T28S R4W CS BT.
16" Laurel bears N.66½°W., 82.1 ft. scribed S1 T28S R5W CS BT.
18" Laurel bears N.13°E., 87.8 ft. scribed S6 T28S R4W CS BT.
No trees near in SW quad.

Doug. County Surveyors Office - Gary Langlitz, Deputy - Pete Earle - June 3, 1974 - C.S. File 56/51-15

Found - Brass cap firmly set near fence cor. The remains of the orig. B.O. BT found by Byron in 1957 is now gone.
The condition of the trees mkd. by Byron is as follows:
18" B.Oak recorded as bearing S.77°E., 27.1 ft. is now down. Found BT tag attached but scribed portion of tree is buried.
16" laurel bearing N.66½°W., 82.1 ft. is now a burnt out shell, all scribing has been destroyed.
18" Laurel bearing N.13°E., 87.8 ft. is now a broken stob. We find plain scribing "BT" on base, scribed area on remainder of tree is buried.

(Cont. Next Page)

