

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. sec. 31; & S. 6 of T29-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, Contract # 44 dated May 30, 1854
(DCSO records Volume 13, Page 5606)

Set 1/4 sec. post at proper distance from which:
 A R.Fir, 4" dia., bears S.18°W., 12 lks. dist.
 A Maple, 6" dia., bears N.55°W., 9 lks. dist

South boundary of T.28-4, surveyed by W.H. Byars, Contract #
376 dated Jan. 22, 1881 (DCSO records, Volume 13 Page 5612.

Marked Fir tree, 4" dia. for 1/4 sec. cor. from which:
 A B.Oak, 18" dia., bears S.85°E., 39 lks. dist.
 A W.Oak, 8" dia., bears N.85°E., 20 lks. dist.

Note: Per note in Byars 1881 survey "In the execution of this
work I found that the old line established for the S bdy of
this Township was glaringly at fault..." Byars set his own
corners. See CS 63/166 BLM opinion file T28-4 (added 4/7/2010)

James W. Byron, Deputy Co Surveyor - April - May 1957
C.S. File 47/180

Found - N.E. BT alive but center rotted. I open upper part
of orig. face and find reversed section of
mark.
 24" B.Oak, down with old face burned out - no scribe
marks found but checks for bearing & dist. to
stump hole. BTs check for size and type of
orig. BTs.
 1/2" I.P. at cor. under N-S fence.
Set - Iron pipe with brass cap at corner marked 1/4 S 31|6
T28S, T29S, R4W, County Surveyors Office 1957.
New BTs - 14" Cedar, bears S.85°E., 50.5' mkd. 1/4 S6 T29S R4W
CS BT.
 18" Cedar, bears N.7 1/2°W., 28.2' mkd. 1/4 S31 T28S R4W

Fd. & used on BLM dependent resurvey by Wayne L. Rogers, Dale
T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H.
Browning, Surveying Technician, under Group #1625 surveyed
Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s)
19802-3)