

PRIMARY CORNER DESCRIPTION East 1/16 Sec. 6 & 31, T27-4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

C.C. Boyer, Deputy Co. Surveyor, June, 1913 For: L. Hatfield
Volume 2 Page 174 - F.B. 35 Pages 3-11

Set post 4x4x36 mkd: CS 1/16 S S6 S31, from which:
A Cedar 12" dia. mkd: CS 1/16 S BT, bears S.59½°E., 35
lks.
A R.Fir, 8" dia., mkd: CS 1/16 S BT, bears S.68 3/4°W., 19
lks.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 1/12/2000 - C.S. File 66/14-3

Found - 12" now 12" dia., 2½ ft. high rotted cedar stump
with a mostly rotted blaze, axe marks & a small
piece of scribing, bears S.59½°E., 23.1 ft. (1913
BT)
8" now 18" dia., 1½ ft. high badly rotted D.Fir
stump no scribing found bears S.68 3/4°W., 12.5
ft. (1913 BT)
Old East-West and South running fence lines
intersect 4 ft. east.
Set - 5/8" x 30" iron rod with yellow plastic cap
protrudes 6" above ground.
23" dia., I.Cedar single blazed low scribed "X CS
BT" bears S.56½°E., 4.7 ft.
10" D.Fir single blazed low scribed "X CS BT" bears
N.4°W., 9.3 ft.