

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Corner for Sections 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract #376 dated Jan. 22, 1881. (DCSO records Vol. 13 Page(s) 5639)

Set Fir Post for the ¼ sec. cor. from which:
A Fir, 10 ins. diam., bears N.16°E., 53 lks.
A Fir, 24 ins. diam., bears N.20°W., 42 lks.

Douglas Co. Surveyors Office, James Byron, Deputy - Dale Mcfarland; John Powell - Aug/Sept 1961 - C.S. File 49/67-28

Found - Orig. 24" now 36" Fir stump N.20°W., 27.7 ft., shows good bark scribing "S". Also find stump of orig. N.E. BT.

Set - Brass Cap at corner mkd: County Surveyor's Office, 1961 ¼ S19|S20 T28S R4W

New BTs- 14" Cedar bears S.28°W. 10.0 ft scribed "¼ S19 CS BT"
9" Cedar bears N.65°E. 15.3 ft scribed "¼ S20 CS BT"

Fd. Ok by K.DeGroot, May 1997 - M124-53

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. - Jan. 2011 - C.S. File 65/74-2

Found - Douglas Co. BC with the following accessories:
36" D.Fir stump bears N.20°W., 27.7' - bark scribe visible.
Record 10" Fir N.16°E., 35.0' - rotted down.
24" I.Cedar bears S.28°W., 10.0' - healed face.
17" I.Cedar bears N.65°E., 15.3' - healed face.

BLM resurvey by George M. Winter & A Bert Skeesick, Cadastral Surveyors, under Group No. 2729, surveyed Nov. 2013/Oct. 2014 - (DCSO records Vol. 58 page(s) 23236-7)

The ¼ sec. cor. of secs. 19 and 20, perpetuated by Byron, in 1961, monumented with an iron pipe, 1¼" dia., firmly set, projecting 18" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree

A fir stump, 44" dia., bears N.25½°W., 29.4 ft., with no marks visible. (Record, N.20°W., 27.7 ft.)

and a bearing trees mkd. by Byron

A cedar, 15" dia., bears N.63°E., 15.3 ft., with a healed blaze.

A cedar, 24" dia., bears S.24½°W., 11.3 ft., with a healed blaze.