

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5642)

Marked Fir, 18" dia., for ¼ sec. cor., from which
A Fir 30" dia., bears N.70°E., 9 lks.
A Fir 60" dia., bears S.65°W., 33 lks.

BLM resurvey by Zirpel and Glenn under Special Instructions dated Aug. 29, 1957 (DCSO records, Vol. 29 Page 12257)

The ¼ sec. cor., determined by the original corner tree, a Fir 27" dia., with illegible scribe marks visible on the bark, from which the two original bearing trees, as follows:
A sawed Fir stump 38" dia., bears N.70°E., 9 lks. dist., no scribe marks visible.
The stump of a down Fir snag, 60" dia., bears S.69½°W., 33 lks. dist., no scribe marks visible. (Rec. S.65°W) and new bearing trees:
A Fir 8" dia., bears N.60¼°E., 36 3/4 lks. dist., mkd. ¼ S5 BT.
A W.Fir 10" dia., bears S.19°W., 202 lks. dist., mkd. ¼ S8 BT.

BLM resurvey by Lynn M. Roseberry, under Group #636 - Survey, May/June 1967 (DCSO records, Vol. 34 Page 14196)

The ¼ sec. cor. occupied by the original corner tree, a Fir, 27" dia., with illegible scribe marks visible in the bark on the SE. face, from which the original bearing trees:
A sawed Fir stump 38" dia., bears N.70°E., 12½ lks. dist., with no marks remaining. (Rec. 9 lks.)
A stump hole, bears S.69½°W., 35 lks. dist., with a burned & rotted down Fir alongside, 60" dia., with no marks remaining. (Rec. 33 lks.)
and bearing trees mkd. by Zirpel and Glenn:
A Fir 20" dia., bears N.60¼°E., 25½ lks. dist., with a healed blaze. (Rec. 26 3/4 lks.)
A W.Fir snag 10" dia., bears S.19°W., 202 lks. dist., with scribe marks ¼ S8 BT visible on open blaze.
and a new bearing tree:
A Madrone 12" dia., bears S.83°W., 19½ lks. dist., mkd. ¼ S8 BT.
The corner is located at the corner of wire fences which extend N. and E.

continued next page

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 2/9/2000 - C.S. File 66/14-20

Found - 18" now 34" dia., D.Fir with faint scribing on SE
trunk. Orig. corner tree.
60" now down & rotted D.Fir "S.65°W., 21.8 ft". OBT.
30" now 34" dia., 2 ft. high D.Fir stump "N.70°E.,
5.9 ft." OBT 1957
8" now 19" dia., D.Fir with a fully healed single
blaze bears N.60¼°E., 16.8 ft. 1957
1957 SW BT now gone.
12" now 16" dia., dead Madrone with a fully healed
blaze S.83°W., 12.9 ft. 1967
New BTs- 10" dia., D.Fir double blazed & scribed "¼ S8 CS BT"
bears S.41½°E., 36.0 ft.
16" dia., I.Cedar double blazed and scribed "¼ S5 CS
BT" bears N.81½°W., 30.0 ft.
9" dia., D.Fir double blazed & scribed "¼ S8 CS BT"
bears S.71°W., 36.3 ft.

Corner lies at the intersection of a N + E running fence
lines.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 11/8/2001 - C.S. File 66/29-24

No problems with BT bearings found.
(BTs were checked as per a request, DCSO JC)

David Edwards - For: Seneca Jones Tbr Co - 4/2010 - M 160-56

Found - 38" dia., Fir corner tree.
16" madrone S.83°W., 12.9' w/HB (Dead)
Remainder as per DCSO 2000 renewal.

FD. as per M160-56 by D Edwards, 11/2014 - M168-67