

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Corner for Sections 8, 9, 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract #376 dated Jan. 22, 1881. (DCSO records Vol. 13 Page(s) 5634)

Set Maple post for the cor. to secs. 8, 9, 16 & 17 from which:

- A Fir, 6" dia. bears N.20°E., 16 lks.
- A Fir, 24" dia. bears S.45°E., 14 lks.
- A Fir, 20" dia. bears S.30°W., 61 lks.
- A Cedar, 12" dia. bears N.35°W., 81 lks.

Douglas Co. Surveyor's Office - James W. Byron, Dale McFarland & J. Powell; Sept. 1961 - C.S. File 49/67-31

Found - No original BTs fd of record. We do find, now 40" Fir properly bark scribed for corner tree. We also find now down & partly rotted 18" Maple bears (left blank in notes) from corner tree, on which I believe I find faint scribe marks. No other BT's found for corner tree. We do find remains of rotten trees and low cut stumps in this area. I use bark scribed tree for corner tree as the scribing seems to be the right age for orig. Also we find, and others have found errors at other corners in this township.

Set - Brass cap at base and on west side of corner tree marked: County Surveyor's Office

		S8	S9	
	1961	S17	S16	T28S R4W

New BTs- 11" R.Fir, bears N.43°W., 25.6 ft. scribed "S8 T28S R4W CS BT"
16" Hemlock, bears S.52°W., 34.4 ft. scribed "S17 T28S R4W CS BT"
36" Cedar bears S.35°E., 37.8 ft. scribed "S16 T28S R4W CS BT"

David Edwards - For: Seneca Jones Tbr Co - 4/2010 - M 160-56

Found - 48" Fir corner tree
The 1961 DCSO BTs are either stumps or gone.
New BTs- 5" dia., fir scribed "T28S R4W S9 BT" bears N.78°E., 9.10 ft.
5" dia., fir scribed T28S R4W S17 BT" bears S.63°W., 24.15 ft.
6 ft. steel post is set 2 ft. East.
6" dia., Hemlock scribed "T28S R4W S16 BT" bears S.32°E., 8.3 ft.