

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 33; Sec. 4 of T 29-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, Contract #44 dated May 30, 1854
(DCSO records Vol. 13 Pg. 5607)

Set 1/4 Sec. post from which:
 A Laurel, 4" dia. bears S.80°E., 32 lks. dist.
 A R.Fir, 18" dia. bears N.3°W., 50 lks. dist.

South boundary of T.28-4, surveyed by W.H. Byars, Contract #376, dated Jan. 22, 1881. (DCSO records Vol. 13, Pg. 5613)

Set Fir post for 1/4 sec. cor. from which:
 A Fir, 12" dia. bears N.25°E., 19 lks. dist.
 A Fir, 12" dia. bears S.9°W., 34 lks. dist.
Note: Per note in Byars 1881 survey "In the execution of this work I found that the old line established for the S bdy of this Township was glaringly at fault..." Byars set his own corners. See CS 63/166 BLM opinion file T28-4 (added 4/7/2010)

G.G. Stewart, Deputy Co. Surveyor. Witnesses: C. Crocker, F. Evans. Jan. 30, 1922 - M 2-4 & Vol. 3, Pg. 113.

Found - Stump that had evidence of blaze. Albert Robinson said that years ago marks were visible.
Set - 5/8" Iron Pipe from this stump.
New BTs - Fir, 14" dia. bears N.26°E., 4.2' dist.
 Fir, 10" dia. bears S.30°W., 33' dist.

James W. Byron, Deputy Co. Surveyor, Dale McFarland, Jim Powell - August 1961 C.S. File No. 49/67-20

Found - 3/4" Iron Pipe at cor. & under E.W. fence. We also find both BTs. recorded. SW BT down. NE BT now 18" Fir snag - shows good scribing "BT"
Set- Brass Cap alongside cor. I.P. & Mkd. County Surveyor's Office, 1961 S33 T28S
 R4W S 4 T29S
New BTs - 8" R.Fir bears S.78°E., 23.8' scribed ¼ S4 CSBT.
 14" R.Fir bears N.49°W., 34.1' scribed ¼ S33 CSBT.