

PRIMARY CORNER DESCRIPTION Center ¼ for Sec. 28.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Burton Holt, for: Sun Studs, June 1977 - M 65-25. ----- Set - 1½"x30" Iron Pipe from which: New BTs - A 6" Fir, bears S.44°W., 23.1' mkd: C¼ S28 BT.           A 10" Fir, bears N.10°E., 11.7' mkd: C¼ S28 BT.</p>
<p>Greg Lang - For: McDonald &amp; Seneca Jones Tmbr Co. 2/2016 - M170-58 ----- Found - 1½" Iron Pipe New - 8" D.Fir bears N.84°W., 47.10', scribed "C¼ S28 BT"       18" D.Fir bears S.23°W. 30.80', scribed "C¼ S28 BT"       9" D.Fir bears S.51½°E. 21.30', Scribed "C¼ S28 BT" Existing 27 D.Fir bears N.12°E., 11.70' (N.10°E. 11.7')</p>
<p>Ken Hoffine - Crew: Gary Angiolet and Ignacio Roman - For: Lone Rock Tmbr - Jan 2019 - C.S. File 65/102-4 ----- Condition report Found - 1½" iron pipe set by Holt in survey M65-25       18" D.Fir bears S.22½°W., 30.8 ft (S.23°W. 30.80 ft)       10" D.Fir bears S.51½°E., 21.4 ft (S.51½°E., 21.3 ft)       24" D.Fir bears N.13¼°E., 11.7 ft (N.12°E., 11.70 ft)       8" D.Fir bears N.84½°W., 47.1 ft (N.84°W., 47.10 ft) Note - Corner lies on steep north facing slope on top of south cut slope of old road grade approximately 15 ft south of road centerline in open timber 0.3 feet above ground level. We ran a random open traverse from the CS 1/16th corner through the center ¼ to the CW 1/16th corner to renew corners and mark property lines for timber management purposes.</p>
<p> </p>