

PRIMARY CORNER DESCRIPTION 1/4 Corner for Sections 27 & 34.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13, Pg. 5626)

Set Fir post for ¼ Cor. from which:
 A Fir, 24" dia. bears N.50°E., 16 lks. dist.
 A Laurel, 14" dia. bears S.50°W., 42 lks. dist.

Doug. County Surveyors Office - G.G. Stewart, Deputy.
Witnesses: Frank Evans, H.Stimpson, C.Crocker. C.S. File no. 5/27, M 2-4 & Vol.3 Pg.113.

Location pointed out by Albert Robinson. BTs gone but we found evidence of old blaze on a down fir. I set Iron Pipe from this down B.T. with Fir marked by it. I marked the following trees.
 New BTs- A Fir, 30" dia. bears N.88°E., 20.2'
 A Laurel, 24" dia. bears S.13°W., 46.0'

B.L.M Resurvey; James E. Jelley, Under Group #1068 Survey, June/Aug.1981 - (DCSO rec. Vol.45, Pg.17378-79)

Found - ½" I.P. set by Stewart, 1922.
 Fnd BTs- A sawed Fir stump, 45" dia. bears N.88°E., 30½ lks. dist. with scribe marks BT visible on opened blaze. (Stewart)
 A Madrone, 30" dia. bears S.11°W., 70½ lks. dist. with axe marks visible on decayed blaze. (Stewart)
 Set - An iron post with brass cap marked:
 T28S R4W
 S 27
 ¼ S 34
 1981

New BTs - A Cedar, 8" dia. bears N.45¼°E., 24½ lks. dist. mkd: ¼ S27 BT.
 A Fir, 16" dia. bears S.47½°E., 52 lks. dist. mkd: ¼ S34 BT.
 Deposit the iron pipe alongside the iron post.

Brass cap & 4 BTs, found OK, Burton Holt, Sept. 1985, M 99-40)
Found OK by G. Lang, August 1999 - M133-18 A & B

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 9/15/1999 - C.S. File 66/12-40

Found - 3¼" dia., BLM brass cap on a 2½" O.D. Iron pipe, protrudes 7" above ground. 1981
 continued next page

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>30" now 36" dia., 2 ft. high rotted D.Fir stump with scribing "BT" visible, bears N.88°E., 20.2 ft. (agrees w/rec.) 1922</p> <p>24" now 30" dia., 5 ft. high rotted Madrone snag with a rotted blaze bears S.11°W., 46.5 ft. (agrees w/1981 BLM rec.) 1922</p> <p>8" now 10" dia., 1 ft. high Cedar stump with an unhealed blaze scribing "4 S27 BT" visible bears N.45¼°E., 16.2 ft. (agrees with rec.) 1981</p> <p>16" now 18" dia., 1½ ft. high D.Fir stump with a fully healed blaze, bears S.47½°E., 34.3 ft. (Agrees w/rec.) 1981</p> <p>New BTs- 6" dia., I.Cedar double blazed & scribed "¼ S34 CS BT" bears S.65°E., 7.4 ft.</p> <p>8" dia., D.Fir double blazed & scribed "¼ S34 CS BT" bears S.8°W., 7.8 ft.</p> <p>16" dia., D.Fir double blazed & scribed "¼ S27 CS BT" bears N.12°W., 8.9 ft.</p> <p>7" dia., I.Cedar double blazed & scribed "¼ X BT" bears N.52°E., 50.3 ft.</p>
