

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 3 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5625)  
-----  
Set post for 1/4 sec. cor. from which:  
    Fir 30" dia., bears S.88°E., 33 lks.  
    Fir 24" dia., bears N.89°W., 20 lks.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - July 1961 - C.S. File 49/67-11  
-----  
Found - Orig. 24" now 36" Fir, down, N.89°W., 13.2 ft. We open and find good scribe marks.  
        Orig. 30" now 40" Fir stump S.88°E., 21.8 ft. shows good bark scribing, not old.  
Set brass cap at cor. mkd: County Surveyor's Office, 1961  
                                    1/4 S3|S2 T28S R4W  
New BTs -7" Cedar bears S.76°W., 9.2 ft. scribed 1/4 S3 CS BT.  
          10" Cedar bears N.37°E., 17.6 ft. scribed 1/4 S2 CSBT

Doug. County Surveyors Office - Gary L. Langlitz, Deputy - P. Earle - Dec. 18, 1973 - C.S. File 56/41-4  
-----  
Found - 1961 DCSO brass cap buried and out of position.  
        7" now 10" I.Cedar bears S.76°W., 9.2 ft. Scars and scribing visible.  
        10" now 16" R.Cedar bears N.37°E., 17.6 ft. Scars & scribing visible.  
        Downed orig. Fir and Fir stump noted in 1961, still in place.  
I reset original brass cap at corner marked "1973".

Found OK by D. Edwards, 2001 - M138-8 and CS 65/34-6A & B

BLM resurvey by George M. Winter, Cadastral Surveyors, under Group No. 2704, surveyed July 2013/Feb. 2016 - (DCSO records Vol. 58 page(s) 23352-3)  
-----  
The 1/4 sec. cor. of secs. 2 and 3, perpetuated by Byron, Deputy County Surveyor, in 1961, reset by Langlitz, in 1973, monumented with an iron post, 1 1/4" dia., firmly set, projecting 1" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees  
    A decayed fir stump, 40" dia., bears N.86 1/2°E., 22.9 ft., with illegible scribe marks visible on the bark. (Record, S.88°E., 21.8 ft.)  
    A roothole bears N.89°W., 13.2 ft., downhill of which is an uprooted, decayed fir stump, 36" dia., with fragmentary scribe marks visible on an opened blaze. cont. next pg

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 3 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and remains of bearing trees mkd. by Byron  
A decayed cedar stump, 20" dia., bears N.37°E., 17.6 ft.,  
with a healed blaze.  
A cedar, 19" dia., bears S.76°W., 9.2 ft., with a healed  
blaze.  
and a new bearing tree  
A cedar, 16" dia., bears S.8¾°E., 20.7 ft., mkd. ¼ S2 BT.  
The geographic position in NAD 1983 (2011)  
Latitude: 43°09'44.016"N. Longitude: 123°08'54.868"W.