

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Pg. 5615-5616)

Set Fir post for corner from which:

- A Fir, 8" dia. bears N.20°E., 69 lks. dist.
- A Fir, 10" dia. bears S.73°E., 23 lks. dist.
- A Fir, 10" dia. bears S.5°W., 39 lks. dist.
- A Fir, 48" dia. bears N.70°W., 339 lks. dist.

John H. Markham Jr. witness L.B. Campbell. For: S.Y.M. Logging Co. Feb. 17, 1958. C.S. File no. 42/330.

Found - 20" Fir, bears N.20°E., 45.5' (original)
24" Fir, bears S.73°E., 15.2' (original) Found bark scribe & remarked.
20" Fir, bears S.5°W., 25.7' (original) I bark scribe S35 BT.

Set -3/4"x20" Iron Rod from which:

New BTs - 5" Fir, bears N.30°W., 2.0' mkd: S26 BT.
18" Cedar, bears S.88°E., 39.0' mkd: S25 BT.

Fd 8/18/76 G. Langlitz - See C.S. 59/18-18 for discrepancies.

Doug. County Surveyors Office - Gregory Quibell, Deputy, John Powell witness. May 18, 1983. C.S. File no. 62/7-7

Found - 3/4" I.Rod flush with ground.
5" Fir, now 8" Hemlock with well healed blaze bears N.30°W., 2.0'.
18" Cedar, now 23" with illegible scribing visible in partially healed blaze, bears S.86°E., 39.7'. (rec. S.84°E., 40.0')
Probable orig. 10" fir now 34" high cut stump with scribing 'S36' in bark per prior renewal. Bears S.69°E., 16.5'. (rec. S.73°E., 15.2')
No sign of orig. scribing.
Probable orig. 48" Fir now 52" stump, no scribing or face visible (however, the bark has been disturbed during logging) bears N.66°W., 22.9' (rec. N.70°W., 223.7') Note: Orig. distance appears to be in error.

Note - Bearings to orig. BTs do not fit, however they are all off 4° in the same direction making the relationship between trees fit well.

continued next page

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

Probable orig. 10" Fir now 36" with rescribing per prior renewal visible (35) bears S.9°W., 24.2. (rec. S.5°W., 25.7) (This BT added 4/20/2016)

Set - Since this area is to be logged soon, I DO NOT SET new monument but do leave found 3/4" iron rod in place.

New - Set spike in center of orig. 48" now 52" fir stump marked 'BO 1' bears N.66°W., 22.9'

Note - Bearing trees are outside of clear cut boundary signs therefore most accessories should be untouched by logging. I double tagged all BTs for better visibility.

Found OK by. R. Rice, Nov. 2002 - M141-27

Ken Hoffine - For: Lone Rock Timber Co - July 2020 - M177-20

Found - 3/4" iron rod (set by Markham 1958)
14" Hemlock at record N.30°W., 2.0 ft. well healed face and county tag at root collar and tag at head height (2002).
31" Cedar bears S.86°E., 39.6 ft (record S.86°E., 39.7 ft) well healed face and tag
23" High cut D.Fir stump bears S.70°E., 16.5 ft (record S.69°E., 16.5) partial rotten face and tag (2002)
52" D.Fir stump bears N.66¼°W., 22.8 feet (record N.66°W 22.9 ft) no visible face. Spike not located county tag (2002).
30" D.Fir bears S.7½°W., 23.3 ft (record S.9°W., 24.2 ft) Bark scribing visible and 3 tags (BLM 1981 COUNTY 1983, WNW 2002)

Note - We notified county of unplaced brass cap and are expecting them to place it soon. All distances and bearings are measured from the iron rod. Corner monument is at ground level and lies on north slope in heavy timber

2