

PRIMARY CORNER DESCRIPTION Cor. #2, Evening Star Placer

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management survey of Mining Claim, Section 15,
Survey No. 979 - 1969-1970 (DCSO records, Vol. 48 Page 18630)

Set an iron pipe, 24" long, 1½" dia., 22" in the ground, mkd.
ES-2-979; from which

A Hemlock 10" dia., bears S.86°00'E., 31.5 ft. dist., mkd.
ES-2-979 BT.

A Cedar 12" dia., bears S.65°00'E., 43.6 ft. mkd. ES-2-979
BT.

A Fir 30" dia., bears N.18°45'E., 31.0 ft. dist., an old
bearing tree, scribing visible.

A Cedar 26" dia., bears S.28°30'W., 21.5 ft. dist., an old
bearing tree, scribing visible.

A Fir 30" dia., bears N.31°21'W., 5.3 ft., an old bearing
tree, blaze not chopped out.

Ray Brown, L.S. #2391 -For: BLM, Nov. 15, 1990 - C.S. File
63/104-71

Found - 1½" Iron pipe at corner.

10" Hemlock, now 18", bears S.86°E., 31.5 ft. has
healed blaze. Added tag.

12" Cedar now 19" bears S.65°E., 43.6 ft. has healed
blaze. Added tag.

30" Fir now 33" bears N.18°45'E., 31.0 ft. has
horizontal healed blaze. Added tag.

26" Cedar now 32" stump bears S.28½°W., 21.5 ft.
Tree cut to low stump, 14" tall, has some sign of
healed blaze and tag.

30" Fir now a burnt and rotted snag, has no visible
blaze or scar, has tag. This tree bears approx.
N.31°W., 5.3 ft.

New BTs -14" Cedar bears N.51°E., 24.0 ft. mkd. ES-2-979 BT.

9" Fir bears N.49°W., 33.0 ft. mkd. ES-2-979 BT.

Corner has no trees within limits in the southwest quadrant.