

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 041010

PRIMARY CORNER DESCRIPTION NNE Cor. Gilmore DLC #41

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, under Contract #28 dated April 20, 1854

Set post, from which
A B.Oak 15" dia., bears S.80°W., 11 lks.
A B.Oak 12" dia., bears N.31°E., 17 lks.

M. Germond, Surveyor - Witn: O. Patterson; Wm. Melton (Gilmore Cemetery) Oct. 7, 1916 - Vol. 3 Pg. 20; Field Book 62 Page 52; and "old" corner book, page 104

Renew corner from one O.B.T. - Set in 3/4" x 1" x 30" Iron bar for NE Cor. DLC 41, T28S R5W, Sec. 11, from which
A W.Oak 5" dia., bears N.75°W., 35.9 ft.
A W.Oak 15" dia., bears N.21½°E., 129.7 ft.
Trees are marked "C.S. DLC 41 BT."

E.S. Woodford, Nov. 1955 - C.S. File 42/115

Found both BTs set by Charlie Roberts in good condition. Stub of one orig. BT found but too rotted and burned out. No scribe marks. Iron rod set by Roberts not found. Set - 1/2" x 48" Iron pipe for corner. Did not mark any new BTs since trees marked by Roberts were still good.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow - For: Office records. - Nov. 1957 - C.S. File 49/21-28

Found - Both BTs as renewed in 1916.
NW BT open, shows scribe marks "C".
NE BT, shows good face, I do not open.
BTs check for bearing and distance & both are alive & in good condition.
Find 1/2" I.P. set by Woodford, 1955, bears North, 1.0 ft. from corner.
Find badly rotted base and stump of orig. SW BT., no scribe marks found. Checks bearing and distance to corner.
I cannot find 3/4" I.Bar set in 1916.
Set Brass cap at cor. mkd. "N.E. Corner D.L.C. 41 T28S R5W County Surveyor's Office, 1957.
No new bearing trees set.