

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5672)

Set ¼ sec. post, from which
A Y.Oak 10" dia., bears S.75°E., 5 lks. dist.
A Y.Oak 11" dia., bears S.43½°W., 20 lks. dist.

Romanso E. Ware, For: A.L. Klassen - April 1976 - M 56-41

Found - 12" Fir BT by Markham but no record. (With blaze & tag)
Established: 12" Fir S.54°W., 7.5 ft. scribed ¼ S31 BT.
New BT - 8" Fir N.33°E., 32.4 ft. "¼ S32 BT".
Set - ¾" Iron pipe.

Found OK by N. Hibbs, May 2003 - M142-33

Greg Lang - For: Roseburg Resources - 6/2005 - M148-4 & C.S. File 65/54/25E

Found - ¾" Iron Pipe set in 1976 per M56-41
Existing 18" D.Fir bears S.55°W., 7.50'
Existing 18½" D.Fir bears N.33°E., 31.55'
New - 9½" D.Fir bears N.55½°W., 26.40' scribed "¼ S31 BT"
7" D.Fir bears S.74½°E., 51.10' scribed "¼ S32 BT"
Note - We set and measured to spikes in the base of all bearing trees; bearings to the trees are based on our 2005 survey referenced hereon.
Corner is located on a northerly slope approximately 550' South of Clarks Branch County road.