

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. secs. 29 and 32

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

| |
|---|
| <p>Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5673)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Y.Oak 12" dia., bears N.17°W., 60 lks. dist. A Y.Oak 12" dia., bears S.16½°E., 39 lks. dist.</p> |
| <p>Doug. County Surveyors Office - James Byron, Deputy - Dale McFarland; J. Powell - Sept/Oct. 1961 - C.S. 49/64-17</p> <p>-----</p> <p>Found - Orig. 12" now 20" B.Oak N.17°W., 39.6 ft., we open & find good scribing "¼" Also find a stump hole that checks for SE BT. Set brass cap at cor. mkd: County Surveyors ¼ S29 T28S R5W Office, 1961 S32</p> <p>New BTs - O.B.T., now 20" B.Oak N.17°W., 39.6 ft. scribed ¼ S29 CS BT. 18" B.Oak bears S.24°E., 23.3 ft. scribed ¼ S32 CS BT.</p> |
| <p>Found OK, Nov. 1976, D. Bentz, M 105-13 ABC</p> |
| <p>Douglas County Surveyors Office - Randall Smith & Stephen Flause - 4/5/95 - C.S. 64/63-1</p> <p>-----</p> <p>Found - 2½" dia DCSO Brass cap on a 1½" OD Iron Pipe, protrudes 9" above ground BC/IP leans .6 east of plumb.</p> <p>Accessories Found - 12" now down and rotted oak that is nearly gone, no scribing or blaze found, root hole bears, N.77°W., 39.6' (agrees w/ rec.) 18" now 23" dia, 15' high live B.oak snag, with a fully healed double blaze, bears S.24°E., 23.3' (agrees with rec.) 1961 DCSO</p> <p>Mon Set- BC/IP returned to plumb position</p> <p>New Accessories - 26" dia B.oak, double blazed and scribed "¼ S29 CS BT", bears N.1°W., 48.4'. 6" dia Madrone, bark scribed "¼ S32 CS BT", bears S.49°E., 14.4' (Brg & Dist taken to root crown) 21" dia D.fir, double blazed and scribed "¼ S29 CS BT", bears N.73°W., 18.3'. 24" dia B.oak, double blazed and scribed "¼ S32 CS BT", bears S.5°E., 90.9'.</p> |
| <p>1</p> |