

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - James E. Freeman, under Contract #1 dated May 28, 1851 (DCSO records, Vol. 13 Page 5602 and 5605)

Set ¼ sec. post, from which
A W.Oak 12" dia., bears N.15°E., 235 lks. dist.
A W.Oak 8" dia., bears S.1°E., 520 lks. dist.

GLO dependent resurvey, W.H. Byars, under contract #376 dated January 22, 1881 (DCSO records, Volume 13 Pages 5610-11)

Set new post as per instructions, bearing trees all standing viz:
White Oak 12" dia., bears N.15°E., 235 lks.
W.Oak 8" dia., bears S.1°E., 5.20 chains.

John Markham, Jr. for: Stomar Lumber Co. - Oct. 21, 1957
C.S. File 42/316

Found - 13" W.Oak stump bears S.2°E., 389.8 ft. O.B.T.
26" W.Oak bears N.15°E., 155.0 ft. Found scribe.OBT.
At Corner point, Set - 2"x24" I.P. in mound of stone.
New BTs -8" W.Oak bears N.10°E., 146.5 ft. dist., mkd. ¼
S19 B.T.
6" W.Oak bears N.43°E., 51.6 ft. dist., mkd. ¼
S19 B.T.
9" W.Oak bears N.32°W., 50.0 ft. dist., mkd. ¼
S24 BT.
20 ft. x 20 ft. x 6 ft. high rock mound in saddle of main ridge bears N.52°W., 245.0 ft.
Note: The most southerly BT should have been at 343.0 ft. but I find it at 389.8 ft. There is a difference of 47.0 ft.
Note also that Government rechainning found south ½ mile 52.7 ft. long.

BLM resurvey by G. Steven Popken, under Group #837, Survey June/July 1874 (DCSO records, Vol. 37 Page 15363)

The ¼ cor. of secs. 19 & 24, on the W. bdy. of the Tp., perpetuated and recorded by John Markham Jr., in 1957. Eng. #2880, monumented with an iron pipe, 2" dia., firmly set, projecting 8" above ground, from which the remains of the original bearing trees:

A sawed W.Oak stump 26" dia., bears N.15°E.,
235 lks. dist., no marks visible.
and bearing trees mkd. by Markham,
(Cont. Next Page)

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Section 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A W.Oak 10" dia., bears N.10°E., 221 lks. dist.,
with healed double blaze.
A W.Oak 9" dia., bears N.40°E., 78 lks. dist.,
with healed double blaze.
A W.Oak 14" dia., bears N.42°W., 75½ lks. dist., with
healed double blaze.
At the corner point, set an iron post, 28" long 2½" dia., 22"
in the ground with brass cap mkd: T 28 S
 1/4
 R 5 W | R 4 W
 S 24 | S 19
 1974

Reset iron pipe alongside iron post.

Fd. cap, I.P, and N.15°E. BT. All other BTs have been cut.
Jeffery S. Whitson, Feb. 1992, Land Partition 1992-0014 ABC

Fd. cap, I.P, and N.15°E. BT. All other BTs have been cut.
Set post alongside of brass cap - Ron Quimby 3/2006 M150-2

Kristian DeGroot - For: Jesse Family LLC - Oct 2012 - M157-64

LAT: 43°07'14.60808" N. LONG: 123°13'33.96233" W.
Found a 1974 USBLM BCIP and accessories by G.S. Popken per a
1974 dependent resurvey.

BLM resurvey by George M. Winter & A. Bert Skeesick,
Cadastral Surveyors, under Group No. 2729, surveyed Nov.
2013/Oct. 2014 - (DCSO records Vol. 58 page(s) 23228-9)

The ¼ sec. cor. of secs. 19 & 24, on the W. bdy. of the Tp.,
monumented with an iron post, 2½" dia., firmly set, flush
with surface of the ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
 An oak stump, size indeterminate, bears N.16½°E., 153.2
 ft., with no marks visible. (Record, N.15°E., 155.1 ft)
There are no new bearing trees available within limits.
 An iron pipe, 2" dia., firmly set, flush with the ground
 surface, with a steel fence post inside is alongside
 the cor.
Corner is located under a newer fence between two braceposts,
extending N. and S.