

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec Cor for 31 & 32; 5 & 6 of T29-6

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5701)

Set post cor. to secs. 5, 6, 31 and 32, from which
A Y.Oak 12" dia., bears S.8 3/4°W., 49 lks. dist.
A Laurel 14" dia., bears S.53°E., 62 lks. dist.
A Fir 8" dia., bears N.42½°E., 52 lks. dist.
A Y.Oak 15" dia., bears N.9 3/4°W., 71 lks. dist.

C.W. Springer, D.C.S. - H.E. Bergh; John Powell - March 13, 1923 - C.S. File 6/27; Vol. 3 Page 140; F.B. 60 Pgs. 79-92

Two original BTs standing, one badly rotted. Other two BTs down. I renew from the two good trees and the stumps of the other two. Drive an Iron pipe 1½" x 48" in ground, from which I marked four new trees as follows:
A Fir 12" dia., bears S.31°50'W., 37.3 ft.
A Fir 10" dia., bears S.69°30'E., 24.0 ft.
A Fir 6" dia., bears N.22°00'E., 11.5 ft.
A Fir 24" dia., bears N.47°00'E., 34.3 ft. (an orig. BT)

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; S.A. Bilow - Nov/Dec. 1958 - C.S. File 49/50-23

Found - 1½" I.P. at corner.
10" now 24" R.Fir S.69½°E., 24.0 ft. shows good scribing, on open face.
24" now 36" Fir stump N.47°E., 34.3 ft., shows good scar. I do not open.
6" now 16" Fir, record N.22°E., 11.5 ft. I find should be N.86°W., 11.0 ft. shows good scar. I do not open.
No trace of Springer's SW BT.
I do not set brass cap at corner.
New BTs - 16" R.Fir N.86°W., 11.0 ft. scribed S31 T28S R6WCSBT
6" R.Fir S.42°W., 44.4 ft. scribed S6 CS BT.
25" R.Fir N.1½°E., 29.1 ft. scribed S32 T28S R6W CS BT.

Fd. ok Feb. 1975, W.S. Barnes, M 55-47.

continued next page

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec Cor 31 & 32; 5 & 6 of T 29-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management resurvey, by Wayne Rogers, under Group #1351, Survey April/May 1987 (DCSO records, Volume 48 Pages 18436-37)

Beginning at the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the tp., perpetuated and recorded by C.W. Springer, Deputy Co. Surveyor in 1923 and further perpetuated and recorded by James Byron, Deputy, in 1958, monumented with an I.P. 1½" dia., firmly set, projecting 6" above ground, from which the remains of an original bearing tree:

A sawed Fir stump 36" dia., bears N.46½°E., 52 lks. dist., with scribe marks R T28S S32 visible on opened blaze. (Rec. N.42½°E.)

and the remains of a bearing tree by Springer:

A sawed Fir stump 25" dia., bears S.71°E., 38 lks. dist., no marks visible.

and bearing trees mkd. by Byron:

A Fir 36" dia., bears N.1¼°E., 43 lks. dist., with healed double blaze.

A Fir 16" dia., bears S.41 ¾°W., 67 lks. dist., with healed double blaze.

A Fir 24" dia., bears N.86¼°W., 17½ lks. dist., with healed double blaze.

At the corner point

Set a Iron post, 28" long, 2½" diam., 22" in the ground, directly over the iron pipe, with brass cap mkd:

T 28 S R 6 W
S 31 | S 32
S 6 | S 5
T 29 S R 6 W
1987

from which a new bearing tree

A Fir 26" dia., bears S.52½°E., 17½ lks. dist., mkd. T29S R6W S5 BT.

Fd OK, BLM Resurvey, by Dale B. Bedell, Surveyed under Group No. 1714. Surveyed July - October 1994. (D.C.S.O. records Vol. 52 Page(s) 19674-75)

Fd. ok by Herm Pieske, July 1998, 1998-0080 A&B

Fd. OK by N. Hibbs, Dec. 2000 - M132-65

continued next page

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. 31 & 32; 5 & 6 of T 29-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Rehabilitation by Timothy J. Moore, Cadastral Surveyor, under Group #1000, surveyed Oct. 26, 2000. (DCS0 rec. Vol. 53 page(s) 20584-8)

The cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the Tp. monumented with an iron post, 2½" dia firmly set, projecting 2" above the ground, with brass cap (properly) mkd. from which the remains of an original bearing tree

A rotted and sawed fir stump, 36" dia., bears N.46½°E., 34.3 ft., with scribe marks T28S S32 visible on a opened blaze.

and the remains of a bearing tree by Springer

A sawed fir stump, 25" dia., bears S.71°E., 25.1 ft., no marks visible.

and bearing trees mkd. by Byron

A fir, 36" dia., bears N.1¼°E., 28.4 ft., with a healed double blaze.

A root hole bears S.41¾°W., 44.2 ft., with a wind blown fir, 16" dia., lying alongside with a healed double blaze.

A root hole bears N.86¼°W., 11.6 ft., with a wind blown fir, 24" dia., lying alongside with a healed double blaze.

and the remains of a bearing tree mkd. by Rogers

A root hole bears S.52½°E., 11.6 ft., with a wind blown fir, 26" dia., lying alongside with scribe marks T29S R6W S5 BT visible on open blaze.

and new bearing trees

A maple, 11" dia., bears N.65½°E., 10.1 ft., mkd. T28S R6W S32 BT.

A fir, 24" dia., bears S.40½°E., 45.2 ft., mkd. T29S R6W S5 BT.

A fir, 13" dia., bears S.21°W., 26.0 ft., mkd. T29S R6W S6 BT.

Corner is located on a SE. slope.

Each new bearing tree has a 2½ inch X 1/4 inch magnetic nail (Mag Nail) driven at the base on the right side-center.

DCS0-GIS Corner visitation - 7/12/2004 - Typed: 1/31/2011 - C.S. File 67/33-1

Monument - GLO/BLM BC/IP 2.5"
Comment - ok

Fd. BC G. Lang 3/2012 - M163-43