

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 24 and 25

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5704)

Set 1/4 sec. post, from which
 A Y.Oak 12" dia., bears N.20 1/2°W., 64 lks.
 A Y.Oak 36" dia., bears S.41°W., 42 lks.

C.G. Gale, Resident Engineer, OSHD, Myrtle Creek - March 11, 1955 - C.S. File 41/345

No mark found at this corner. Original bearing trees were destroyed in clearing the highway right of way. After grading work on the hwy was completed, the cor. was set from ties to the old bearing trees and coordinates from the hwy centerline. A 3/4" round iron pin set in concrete marks the corner. A painted white 4" x 4" wood post set by the corner as a finder. Bearing trees marked:

 10" Madron (Mtn. Laurel) N.82°37'E., 68.7 ft.
 10" B.Oak N.22°03'W., 81.2 ft.

The cor. is on the easterly side of the hwy. at the bottom of an approx. 55 ft. high fill. It is inside the hwy. R/W and approx. 20 ft. from the fence.

Reported by State Hwy. Engineer, May 11, 1955, that the 1/4 sec. cor. to secs. 24 and 25 has had a slide by it that has taken out the corner and the NE witness tree. (CS File 41/345)