

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 054060

PRIMARY CORNER DESCRIPTION SE Cor. Hull DLC #54

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855

Set post, from which
A Fir 10" dia., bears N.20°W., 37 lks.

G.G. Stewart, Deputy - For: Bogard Real Estate - Wit: C. Crocker; J.H. Porter - Vol. 3 Pg. 126; C.S. 3/40 & 5/22;

Reset from burned O.B.T. Drove Iron pipe and marked:
Maple 6" dia., bears S.46°E., 12.4 ft.
W.Fir 16" dia., bears N.42½°W., 47.6 ft.

Doug. County Surveyors Office - James W. Byron, Deputy - April 1957 - C.S. File 47/176; RM 1-15

Found - 3/4" I.P. at corner and 6" Maple, now 18", S.46°E., 12.4 ft. - reverse scribing visible.
Blazed and Scribed:
24" W.Fir N.76°W., 9.3 ft. "SE C1 54 CS BT".
Corner 30 ft. south of logging road.

Doug. County Surveyors Office - A. Victor Cangie; Karen Cheney - Aug. 26, 1976 - C.S. File 59/18-24

Found - 3/4" x 29" Iron pipe.
An orig. 10" D.Fir, now 23" snag, N.20°W., 24.4 ft. Tree shows large deep healed scar.
A 16" Maple, S.46°E., 12.4 ft. face is rotted out & tree is dying.
A 24" now 34" W.Fir, N.76°W., 9.3 ft. Tree is alive and shows good scar.
Set a 1" x 30" brass cap mkd. Douglas Co. Surveyor DLC 54
1976 SE Cor. |
T28S R7W
Replaced found I.P. on East side of brass cap.
New BTs -A 6" D.Fir bears N.2½°E., 15.1 ft. mkd. "SE DLC 54 CS BT" in a double blaze.
A 9" D.Fir bears S.35½°E., 33.5 ft. mkd. "SE DLC 54 CS BT" in a double blaze.

Found OK, Feb. 1984, O.S.H.D., C.S. File 58/164-8

Douglas County Surveyors Office - Randall W. Smith, Stephen J. Flause - Oct. 12, 1993, C.S. File 64/47-3

Found - 2½" DCSO Brass Cap on a 1½" O.D. iron pipe protruding 6" above ground. (1976 DCSO) CONT.

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 054060

PRIMARY CORNER DESCRIPTION SE Cor. Hull DLC #54

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

3/4" I.D. iron pipe protruding 5" above ground is found along easterly edge of DCSO BC/IP (1972 DCSO)

Accessories Found -

- 10" now 23" dia. 18 ft. high D.Fir snag with a healed previously opened blaze, bears N.20°W., 24.4 ft. (orig. BT)
- 24" now 34" dia. 5 ft. high D.Fir stump with a fully healed single blaze, bears N.76°W., 9.3 ft. (1957 DCSO)
- 6" now 5 ft. high rotted Maple stump of indeterminable size, no blazes or scribing visible, bears S.46°E., 12.4 ft. (1922 DCSO) Note- stump is sprouting new growth.
- 6" now 14" dia. D.Fir with a fully healed double blaze, bears N.12½°E., 15.1 ft. (rec. N.2½°E., 15.1 ft.) (1976 DCSO)
- 9" now 15" dia. D.Fir with a fully healed double blaze, bears S.35½°E., 33.5 ft. (1976 DCSO)

New Accessories -

- 9" dia. D.Fir, double blazed and scribed "SE DLC 54 CS BT" bears N.48°W., 28.1 ft.
- 9" dia. D.Fir, double blazed and scribed "SE DLC 54 CS BT" bears N.60°E., 3.5 ft.

Fd ok by G. Lang. 12/2010 - M161-58