



TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 100122

PRIMARY CORNER DESCRIPTION E. ¼ Cor. Sec. 36 only, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Doug. County Surveyors Office - S.J. Flause; R.W. Smith  
June 10, 1987 - C.S. File 62/45-12

-----  
Found - 1½" dia. 1961 DCS0 brass cap, properly mkd., on a 1"  
I.D. iron pipe, firmly set, & protruding 16"  
above ground.

1" dia. Iron pipe from Cole, not evident.

From orig. 1855 Hathorn survey, a 24" Fir dia., now  
a 36" dia. 3 ft. tall Fir stump with the scribing  
"BT" visible in an opened blaze, bears N.87°W.,  
21.2 ft. (as per rec.)

24" B.Oak searched for and not found.

SE 16" Fir not searched for.

From 1924 resurvey, no evidence of SW BT found.

12" R.Fir now a 12" dia. 2 ft. tall Fir stump with  
rotted blaze on fallen trunk, no scribing found,  
bears S.41°E., 54.8 ft. as per rec. (Byron)

Monument position is perpetuated as found.

New BTs - 11" D.B.H. D.Fir scribed "¼ S36 CS BT" on a double  
blaze bears N.74½°W., 40.2 ft.

10" D.B.H. W.Fir scribed "¼ S36 CS BT" on a double  
blaze bears S.49½°W., 22.9 ft.

Monument lies in break of steep easterly slope approx. 100  
ft. ± , S.09°W., from N-S switch back in private road.