

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6 only, T28-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Nathaniel Ford, Under Contract #44 dated May 30, 1854 (DCSO records, Volume 12 Page 5222)

Set a post, cor. of secs. 1 and 6, from which
 A B.Oak 8" dia., bears S.15°E., 150 lks. dist.
 A B.Oak 8" dia., bears S.35°W., 130 lks. dist.

GLO survey by Fred Mensch, Under Contract #109 dated 1924 (DCSO records, Volume 14 Page 5878)

Intersect the point for standard cor. of Tps. 28S., Rgs. 7 and 8 W., established by Ford, located by Hathorn's record tie from the Hathorn standard cor. of tps. 28S Rgs. 7 & 8 W., then corrected to true position with reference to the original SW bearing tree. This tree has fallen and is decayed to such an extent that the marks are gone and could not be positively identified without the Hathorn tie. No evidence could be found of the SE bearing tree. At the exact cor. point, Set an iron post, 3 ft. long, 3" dia., 27" in the ground, for standard NW cor. of T. 28 S., R. 7 W. only, with brass cap marked.

	S 6	
	T 28 S	
	R 7 W	1924
	S C	

from which (new bearing trees)
 A W.Oak 9" dia., bears S.41½°E., 170 lks. dist., marked
 S C T28S R7W S6 BT.
 A Fir 10" dia., bears S.8°E., 108 lks. dist., marked
 S C T28S R7W S 6 BT.

Original bearing tree, stump hole of black Oak, bears S.35°W., 130 lks. dist.
 Standard cor. of Tps. 28 S., Rs. 7 and 8 W., established by Hathorn, now restored as cor. of Tps. 28 S., Rs. 7½ and 8 W., bears S.33°48'W., 10.55 chs. dist.

H.L. Eppstein, Co. Surveyor - June 30, 1930 - M 1-73; C.S. File 14/44 and 14/59; Vol. 4 Page 11

Standard government pipe.
 Witness trees:
 10" W.Oak S.41°30'E., 112.0 ft.
 15" Fir S.80°30'E., 71.1 ft.

Found OK, H.Stockhoff, M 87-69, May 1981

(Cont. Next Page)

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6 only, T28-7

Alias	Description

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - May, 6 1997 - C.S. 64/74-26

Mon. Fd.- 3½" dia. Brass cap on a 3" O.D. iron pipe
protrudes 6" above ground. (1924)

Accessories Fd.-

10" now 28" dia. down broken rotted D.Fir, scribing
found "T28S R7W S6 BT", bears S.8½°E., 71.1'
(agrees with 1930 rec.) 1924

(NOTE: an error was made on corner tie to above D.Fir
per survey M 1-73 and 1930 corner renewal. A
check of field book was made, bearing should be
S.8½°E., this agrees closely w/ 1924 GLO bearing
of S.8°E., rec. S.80½°E., is in error.)

New Accessories -

NE corner of barn bears N.42°E., 22.8'.

16" dia. W.Oak, double blazed and scribed "SC
T28S R7W S6 CS BT", bears S.13°W., 51.9'.

15" dia. W.Oak, double blazed and scribed "SC
T28S R7W S6 CS BT", bears N.27½°W., 71.9'.

19" dia. B.Oak, double blazed and scribed "SC
T28S R7W S6 CS BT", bears N.76°W., 82'.

Corner is located inside a barn