

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 7

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A. Boyer, Nov. 1958 - M 13-19

Iron Pipe.

25" W.Fir N.80°W., 39.9 ft. scribed Cen S7 1581 BT.

15" Cedar S.87°E., 23.5 ft. scribed Cen S7 1581 BT.

Corner 180 ft. North of top of ridge on N. slope and 117 ft. East and 38 ft. South of 36" Fir blazed about 1930.

BLM dependent resurvey by Bryan S. Seibold, & Robert J. Chappel, Cadastral Surveyor, under Group #1585, surveyed May 1991/May 1994 - (DCSO records Vol. 52 Page(s) 20033-4)

The center ¼ sec. cor. of sec. 7, established by Boyer, in 1958, this position was used but not recorded by an unofficial Bureau of Land Management Administrative Survey in 1976, and is accepted as the corner; monumented with an iron pipe, 1½" diam., firmly set, projecting 1" above ground, with a steel fence post set alongside, from which a bearing tree mkd. during the Administrative Survey:

A cedar, 23" diam., bears N.79°E., 32 lks. with healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" diam., 22 ins. in the ground, directly over the iron pipe, with brass cap mkd.

T28S R7W

C1/4 S7

1991

and new bearing trees

A fir, 8" diam., bears S.23°E., 24½ lks., mkd. C1/4 S7 BT.

A fir, 12" diam., bears S.50½°W., 37 lks. mkd. C1/4 S7 BT.

Deposit a white "DEEP-1" magnetic marker at the base and reset a fence post alongside the stainless steel post.