

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 14 Page 5779)

-----

Set quar. sec. post, from which  
 A B.Oak 18" dia., bears S.50°E., 79 lks. dist.  
 A Laurel 30" dia., bears S.18°W., 27 lks. dist.

GLO resurvey by Mensch, 1924 - (DCSO records, Vol. 14 Pg. 5895)

-----

Intersect the point for 1/4 cor. located by record measurement from the original bearing trees, on which the marks are plain. At the exact cor. point  
 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd:

$\frac{1}{4}$   
 S 7 | S 8  
 1924

from which, original bearing trees:  
 A B.Oak 24" dia., bears S.50°E., 79 lks. dist.  
 A Laurel 40" dia., bears S.78°W., 27 lks. dist.  
 New Bearing Trees:  
 A Fir 16" dia., bears S.40°E., 22 lks. dist. mkd. 1/4 S8 BT  
 A Fir 6" dia., bears N.17°W., 23 lks. dist. mkd. 1/4 S7 BT.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - May 1961 - C.S. File 52/79-13

-----

Found - Both BTs, 1924 survey and orig., now 30" B.Oak, previously opened, shows good scribing "BT".  
 Find bearing should be S.30°E., not S.50°E.  
 1" I.P. at corner said by Monger to have been set by Boyer. Monger also states that he has known about this corner for 25 years and that he has never seen a brass cap here.

Set Brass cap alongside I.P. mkd: County Surveyor Office 1961  
 $\frac{1}{4}$  S7 | S8 T28S R7W

Bearing trees OK.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause; May 23, 1994 - C.S. file 64/51-20

-----

Monuments Found -  
 2 1/2" dia. Brass cap on a 1 1/2" O.D. iron pipe protrudes 16" above ground. (1961) BC. marked with wrong Tship. & Rng.  
 1" I.D. iron pipe protruding 3" above ground is found along south edge of BC/IP.

(Cont. Next Page)

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 and 8

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Accessories Found -

18" now 1 ft. high rotted Oak stump of indeterminable size, old axe marks and blaze visible, no scribing found. Bears S.30°E., 52.1 ft. Orig. BT.

30" now 40" dia. live 30 ft. high Madrone snag, shows evidence of a previously opened now burned out blaze no scribing found. Bears S.78°W., 19.2 ft. (rec. S.78°W., 17.8 ft.) Orig. BT.

16" now 24" dia. 3½" ft. high D.Fir stump with a fully healed single blaze, bears S.43°E., 14.5 ft. (rec. S.40°E., 14.5 ft.) 1924 BT.

6" now 17" dia. D.Fir with a fully healed single blaze, bears N.17°W., 15.2 ft. 1924 BT.

Monuments Set - 1961 Brass cap was mis-marked, we mark BC to show correct township and range.

New Accessories -

22" dia. D.Fir, double blazed and scribed "1/4 S7 CS BT" bears S.37½°W., 8.0 ft.

6" dia. W.Fir, double blazed and scribed "1/4 S8 CS BT" bears N.51°E., 9.0 ft.

6" dia. Cedar, double blazed and scribed "1/4 S7 CS BT" bears N.64°W., 33.5 ft.

Note - Corner lies 30 ft. SW of a dirt road. Position of corner appears to have been determined by Mensch at an intersection of orig. distance. Evidence in field depicts blazes facing BC/IP.

Fd. & used on BLM dependent resurvey by Bryan S. Seibold, & Robert J. Chappel, Cadastral Surveyor, under Group #1585, surveyed May 1991/May 1994 - (DCSO records Vol. 52 Page(s) 20020)