

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 14 Page 5767)

-----  
Set a post, cor. of secs. 3, 4, 9 and 10, from which  
A B.Oak 8" dia., bears S.12°E., 125 lks. dist.  
A B.Oak 15" dia., bears S.5°W., 125 lks. dist.  
A W.Oak 8" dia., bears N.20°W., 137 lks. dist.  
A B.Oak 12" dia., bears N.12°E., 150 lks. dist.

G.G. Stewart, Deputy Co. Surveyor - A.O. Strickland; A. Dyset; A. Erickson - March 16, 1922 - Vol. 3 Pg. 108

-----  
Establish by intersection of lines between quarter corners.  
Found no evidence of original corner.  
Set Iron pipe, about 8 ft. from edge of Co. Rd.  
Marked:  
B.Oak 16" dia., bears N.63°E., 71.9 ft.  
B.Oak 10" dia., bears N.11°W., 24.7 ft.  
No other trees available.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - March 1961 - C.S. File 49/50-35

-----  
Found - ½" I.P. over ½" I.P. at corner and record NW BT, shows good scar.  
We also find rotted stump, NE BT.  
New BT - 11" W.Oak bears N.6½°E., 31.9 ft. scribed S3 T28S R7W CS BT.

Fd. OK, July 30, 1979, DCSO office, C.S. 60/34-7

BLM resurvey by Rogers and Bishop, under Group #1124, Survey, April 1983-Jan. 1984 (DCSO records, Vol. 46 Pgs. 17748-49)

-----  
Cor. reestablished at proportionate dist. by Stewart, 1922 monumented with an I.P. ¾" dia., firmly set flush with the ground, and further perpetuated and recorded by Byron, 1961. There is no remaining evidence of the original cor. This point is accepted as the cor., from which a bearing tree mkd. by Stewart:  
A B.Oak 13" dia., bears N.10°W., 38 lks., with a healed blaze.  
and a bearing tree mkd. by Byron  
A W.Oak 12" dia., bears N.4½°E., 48 lks. dist., with healed double blaze.  
At the Corner Point  
Set an Iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

T 28 S R 7 W  
S 4 | S 3  
S 9 | S 10  
1983

from which a new bearing tree and a reference monument  
An Iron post, 28" long, 2½" dia., set 24" in the ground,  
for a reference monument, bears S.59 ¾°E., 99 ¾  
lks. dist., with brass cap mkd. T28S R7W RM S10 65.8  
FT. TO COR 1983 and an arrow pointing to the cor.  
A B.Oak 32" dia., bears S.38 ¾°W., 289 lks. dist. mkd.  
T28S R7W S9 BT.  
Deposit the ¾" Iron pipe alongside the iron post.

Fd. Ok - March 31, 1994 - Maurice E. Farr - M118-67  
Fd. OK, Aug. 1995, by D.Bentz - M122-54  
Fd. OK, Mar. 1997, by D.Bentz - M127-6  
Fd. OK, Aug. 2002, by D. Edwards - M140-61  
Fd. BC by N. Hibbs, 10/2009 - M160-21

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and  
Jeff Lorsung - 8/7/2025 - C.S. File 67/61-9

-----  
Found - BLM Brass cap proj 4"  
13" dead B.Oak N.10°W. 25.1 ft (Rec 38 lks)  
22" W.Oak N.4½°E. 31.7 ft (Rec 48 lks)  
41" B.Oak S.38¾°W. 190.7 ft (Rec 289 lks) falls in  
yard with swing attached.  
BLM brass cap reference monument S.59¾°E. 65.8 ft  
(Rec 99¾ lks) marked "T28S R7W RM S10" 65.8 ft to  
cor 1983 with arrow pointing to corner.  
Mon fall in top edge of northerly ditch 5 ft from  
edge of Larson Rd.

Notes - Reference mon is south of road fill approx 9' from  
shoulder.

Compass decl. 14¾°E.  
O CRS COORDINATE SYSTEM  
COTTAGE GROVE-CANYONVILLE ZONE  
43°09'22.47701 N.  
123°31'18.92956 W.