

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 700160

PRIMARY CORNER DESCRIPTION N 1/16 cor. to secs. 36 & 31 Of T27-7

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Douglas County Surveyors Office - H.L. Eppstein, Co. Surveyor  
June 30, 1930 - M 1-73

-----  
Cor. Set- Cedar Post 3"x3"x30"  
BT Set - 12" dia. R.Fir, bears S.31°30'W., 13.6'

Douglas County Surveyors Office - Randall Smith & Stephen  
Flause - April 30, 1997 - C.S. 64/74-22

-----  
Mon. Fd.- Fence corner post at the intersection of a south  
and west running fence lines (not of record)  
Fence is old and of the same condition and  
type of fence found at corner locations in  
near area.

Cedar post set per M1-73 not found.

Accessories Fd.-  
12" R.Fir now 12" dia. 3' high rotted D.Fir, with  
axe marks and rotted blaze. (no scribing  
found), bears S.31½°W., 13.6' from plumb  
position of fence corner post. (agrees with  
rec.) 1930 DCSO

20" dia. Cedar, with a rusted forrest service  
location poster marked T27S R8W with a nail  
indicating the N 1/16 cor. on east side of  
sec. 36 other marks are unreadable. Cedar  
tree and tag are approx. west 5' of fence  
corner. Source unknown (looks old)

Mon. Set - No monument set as corner falls at a point of an  
existing fence corner.

New Accessories -  
9" dia. W.Fir, double blazed and scribed "N 1/16  
S31 CS BT", bears S.51°E., 14.6'.  
10" dia. Madrone, double blazed and scribed "N  
1/16 S36 CS BT", bears S.4°W., 28.7'.  
7" dia. Madrone, double blazed and scribed "N  
1/16 S31 CS BT", bears N.1½°E., 18'.