

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 903100

PRIMARY CORNER DESCRIPTION South 1/4 Cor. sec. 33 T27-7 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy under Contract #57 dated April 12, 1855 (DCSO records, Volume 12 Page 5224)

Set ¼ sec. post, from which
A B.Oak 15" dia., bears S.53°W., 15 lks. dist.
A B.Oak 18" dia., bears N.53°E., 28 lks. dist.

(See also Volume 12 Page 5220 for Ford's ¼ corners in 1854)

GL0 survey by F. Mensch, Contract #109 dated 1924 (DCSO records, Volume 14 Page 5845)

Intersect the ¼ sec. cor. of sec. 33, located by record bearing and distance from the original NE. bearing tree, blazes show plainly. The original SW tree is not found. At the exact cor. point, Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ sec. cor. sec. 33, with brass cap marked:
AP 10
¼ S33
1924

from which
(Old bearing tree) A B.Oak 24" dia., bears N.53°E., 28 lks. dist. remarked ¼ S33 BT.
(New Bearing tree) A B.Oak 16" dia., bears N.38°W., 39 lks. dist. marked ¼ S33 BT.
(The corner established by Ford for ¼ sec. cor. of sec. 33, restored as angle point, bears N.36°43'E., 2.26 chs.)

Doug. County Surveyors Office - James W. Byron, Deputy; Milo Godfrey; Clete Putnam - Feb. 1961 - C.S. file 49/79-29

(Angle Point #10)
Found - Brass cap and both BTs. NE BT, face rotted.
New BT - 17" Laurel bears N.9½°E., 34.9 ft. scribed ¼ S33 CS BT.

Fd. & used BLM resurvey by Philip G. Griffin, Cadastral Surveyor, under Group # 1529, surveyed April/July 1990 (DCSO Records Vol. 50 Page(s) 19149)