

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

DLC Survey by J.A. Burnett, under Contract #75 dated Dec. 19, 1856 - (DCSO Records, DLC Volume Page 520)

Set a post, from which
A W.Oak 10" dia., bears N.5°W., 247 lks.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Jan. 24, 1969 - C.S. File 54/78

Looked for, not found.
From computed point taken from our traverse, we find no trace of orig. BT or any unrecorded BTs or GLO monuments. This point falls in old cultivated field. Old tree line course N., would indicate the possibility of an old fence line. Old fence bears South 10 ft. at easterly end of gate. Creek call of 2.70 chains would fit this point real well.

Douglas Co. Surveyors Office - Stephen J. Flauser - Mike Koch - June 8, 2012 - C.S. File 67/36-9

Reported as not found.
No monuments found. Using a private surveyors determined approx. cor. location we check wide area with metal detector for evidence of possible unrecorded 1924 GLO monument (see C.S. File 54/78) but find nothing.
We thoroughly examine fallen and rotted oak snag which agrees reasonably well in bearing & distance with above noted cor. position. Other oaks in area are too young to be BT.
Note - Stream call fits well with Surveyors POSITION.
Compass decl. 15½°E.

Carl Sweeden - For: Emma Wageman Trust - June 2012 - M163-67

New - e"x30" I.Rod w/red plastic cap stamped "SWEEDEN LS 2752", flush & 2.0' south of E/W wire fence: established the following BTs:
19" W.Oak, N.9°W., 49.3' to spike in bole, scribed DLC 37 BT", tagged
13" W.Oak, N.25°E., 32.1' to spike in bole, scribed DLC 37 BT", tagged
15" W.OAK, N.84°E. 45.25' to spike in bole, scribed DLC 37 BT", tagged
6 W.Fir, S.2°E., 56.2' to spike in bole, scribed SSE DLC 37 BT, tagged