

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 041040

PRIMARY CORNER DESCRIPTION S SE Cor Wm Weekly DLC #41

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by J.A. Burnett, under Contract #75 dated Dec. 19, 1856 - (DCSO Records, DLC Volume Page 523

Set a post, from which
A Fir 14" dia., bears N.45°W., 63 lks.

F.J. Cole, Deputy - Wit: Chas. Wilson; S.A. Gurney; J.W. Gurney - Jan. 1915 - Vol. 2 Pg. 268; Field Book 37 Pgs. 2-5 (and "old" Renewal Vol. 1 Pg. 116)

Renew corner from stump of original BT, and marked:
A W.Fir (?) dia., N.65°E., 8 lks.

A. R. Evans - Wit: J.E. Clinton - Dec. 1951 - M 9-41

Set 1/2" Iron pipe for corner by proper measure with Cole survey, 1915. Blazed and scribed:
A 30" Fir S.40°E., 49.0 ft. mkd. "Ext. L Cl. 41 RE 2741 BT"

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew March 1966- C.S. File 52/79-18

Found - 3/4" Iron pipe at DLC corner.
30" D.Fir now 34", S.40°E., 49.0 ft., bark scribed visible.
Set Brass cap at cor. alongside I.P., mkd:
County Surveyors Office
T 28 S R 8 W
Ext. L DLC 41/
1966

Reblazed and rescribed:
34" D.Fir S.40°E., 49.0 ft. scribed Ext. L DLC 41 CS BT.
Corner lies in fence corner, fences running North and West.