

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by J.A. Burnett, under Contract #75 dated Dec. 19, 1856 - (DCSO Records, DLC Volume Page 523)

Set a post, from which
A Fir 8" dia., bears N.30°W., 25 lks.

J.W. Cole, Deputy - Wit: Wilson and Gurney - Jan. 1915 - Vol. 2 Pg. 268; Field Book 37 Pgs. 2-5 (and "old" cor. book, Pg. 116)

Renew corner from decayed remains of original tree.
Set a Fir post and two rocks for corner, from which
A Fir 30" dia., bears N.43¼°W., 135 lks.

A.R. Evans - Wit: J.E. Clinton - Dec. 1951 - M 9-41

Found stump of Fir BT, N.43¼°W., 89.1 ft.
Set Ford axle for corner. Blazed and scribed new BTs:
16" Hemlock N.25 3/4°W., 55.0 ft.
12" Hemlock N.2½°W., 34.0 ft.
Both marked S.E. CL 41 R.E. 2741 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - March 3, 1970 - C.S. File 52/79-40

Found - Axle at corner
16" Hemlock, now stump, N.25 3/4°W., 55.0 ft., found scribe, part of "T".
12" Hemlock now snag, N.2½°W., 34.0 ft.
Fir stump, N.43°W., 89.1 ft., bark scribed "T" visible.

Set Brass cap at cor. mkd: County Surveyors Office
(Set alongside axle)

T 28 S R 8 W
S.E. Cor. |
D.L.C. #41
1970

New BTs- 12" Hemlock S.38°W., 7.4 ft. mkd. S.E. DLC 41 CS BT
8" W.Fir N.21°W., 52.3 ft. mkd. S.E. DLC 41 CS BT.
Corner lies 10 ft. South of creek.

BLM resurvey by Boyd W. Peterson, under Group #1364, Surveyed May/Aug. 1987 - (DCSO records Vol. 48 Page(s) 18409-10)

The SE. cor. of DLC #41, perpetuated and recorded by Cole, in 1915, from original evidence no longer in existence, and further perpetuated and recorded by Evans, in 1951, and by
(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 041060

PRIMARY CORNER DESCRIPTION E SE Cor Wm Weekly DLC #41

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Powell in 1970, monumented with an iron pipe, 1¼" dia, (with an axle 1" dia., alongside), firmly set, projecting 10" above ground, with brass cap mkd. in 1970
from which the remains of the bearing tree mkd. by Cole
A sawed Fir stump 34" dia., bears N.43°W., 137 lks. dist., no marks visible on open blaze.
and the remains of a bearing tree mkd. by Evans
A rotted Hemlock stump, size indeterminate, bears N.25¼°W., 83 lks. dist., no marks visible.
and the remains of the bearing trees mkd. by Powell
A W.Fir 20" dia., bears S.40°W., 11 lks. dist., with healed blaze.
A rotted Fir stump, size indeterminate, bears N.22°W., 77½ lks. dist., with a rotted Fir log alongside, with scribe marks SE DLC 41 CS BT visible.
and a new bearing tree
A Fir 20" dia., bears N.20¼°W., 115 lks. dist. mkd. SE DLC 41 BT.

Fd. OK, Dec. 1992 by D. Bentz - M 116-57