

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T28-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5788)

-----  
Set ¼ sec. post, from which  
A Fir 40" dia., bears N.80°E., 11 lks. dist.  
A Fir 40" dia., bears N.20°W., 18 lks. dist.

Ben B. Irving, Deputy Co. Surveyor - Wit: N.E. Richardson; Harmson - Jan. 25, 1939 - C.S. File 15/14 (and "old" cor. book, Page 117)

-----  
Set a 4" square Fir post for the corner, scribed ¼ S on the S. face., from which  
An Orig. 40" Fir bears N.20°W., 18 lks., blazed and marked in the bark "¼ S36 CS BT".  
Other orig. BT, only stump remains.  
New BT, Cedar 24" dia., bears S.45°E., 68 lks., blazed and scribed "¼ S31 CS BT"

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey, crew - Sept. 10, 1957 - C.S. File 49/12-13

-----  
Found - 1" axle with hub at corner and both orig. BTs.  
The 40" now 50" Fir, N.20°W., 11.9 ft., uprooted.  
I open old scar at base & find good scribing "B"  
The orig. NE. Bt has just a part of shell of old stump left. Shows burl facing corner.  
Both BTs check for bearing and distance.  
26" Cedar S.42½°E., 43.6 ft. scribed ¼ S CS BT. (1939)  
14" W.Fir S.38°W., 33.4 ft. shows old face, may be BT.  
New BT - 5" W.Fir S.61½°W., 24.3 ft. scribed ¼ S36 DCS BT.  
This corner probably renewed about 10 or 15 years ago.  
Probably renewed by Coos Co. Surveyor.

BLM Resurvey by William W. Glenn, Cadastral Surveyor, under Group #'s 350 and 420, surveyed April/June 1959 - (DCSO records Vol. 30 Page(s) 12850-51)

-----  
The ¼ sec. cor., perpetuated and recorded by Byron in 1957, monumented with an axle, 1" dia., firmly set, 8" above ground, from which the original bearing trees:  
A rotted Fir stump 40" dia., bears S.85°E., 11 lks. dist.  
(Rec. brg. S.80°E.)  
(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 cor. for Sec. 31; & S 36, T28-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A down Fir 50" dia., bears N.20°W., 18 lks. dist. with scribe marks BT visible on an opened blaze. and a locally established bearing tree:

A Cedar 27" dia., bears S.43¼°E., 66 lks. dist., with scribe marks ¼ S C S BT visible on open blaze. and a bearing tree established by Byron:

A W.Fir 5" dia., bears S.59½°W., 36½ lks. dist., mkd. ¼ S36 DCS BT.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

T 28 S  
¼  
R 9 W | R 8 W  
S 36 | S 31  
1959

Deposit axle alongside iron post.

Fd. OK by K. Hoffine, Nov. 1999 - M133-58

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 12/23/2014 - C.S. File 65/87-30

-----  
Found - 3¼" brass cap on a 2½" iron pipe, 0.4" tall in good condition and solid in the ground. There is a ring of sandstone rocks placed around this monument. We set a D.Fir post 3' north and paint the top in blue. 1959

An 8" hum on a 1" axle, 1.0' tall, in good condition and solid in the ground, driven in on the north side of the BCIP. Byron thinks this axle was set by the Coos County Surveyor, but we are unable to find any record of this. 1957

A 17" R.Cedar snag, S.41°E., 43.72' to left side center. We find visible scribes and a 1959 BLM tag in place. We paint the face and a band around the snag in blue. Poor condition. 1957

A 14" G.Fir stump, S.61°W., 24.21' to right side center. We find no marks, but there is a BLM tag in place. We paint "BT" on the stump in blue. Poor condition. 1957

New BT - A 34" G.Fir, N.55°E., 37.02' to a nail at left side center. We bark scribe "¼ S31 BT". We paint the scribes and a band around the tree in blue and attach a yellow Coos County tag.

Compass decl. 17°E.