

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page 5824)

Set post 4 ft. long, 4" dia. and 1 ft. in ground, for 1/4 sec. cor., from which

A Fir 72" dia., bears S.35°W., 11 lks. dist.

A Fir 66" dia., bears S.60°E., 6 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - July/Aug. 1957 - C.S. File 49/5-7

Found both original BTs. I open each face. The SE. BT shows old rotted blaze. The SW. BT shows good scribing "BT".

Set Brass cap at cor. mkd: County Surveyors Office

T 28 S R 8 W

1/4 S 18 | S 17

1957

(BTs added 7/14/2021)

New BTs- 10" Hemlock 34 1/2°W., 25.2' scribed 1/4 S 18 CS BT

9" Hemlock N.29°E., 43.3' scribed 1/4 S 17 CS BT

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15090-91)

The 1/4 sec. cor., perpetuated and recorded by Byron in 1957, monumented with an iron pipe 2" dia., firmly set, protruding 10" above ground with brass cap mkd. in 1957,

from which original bearing trees

A Fir 75" dia., bears S.60°E., 6 lks. dist., no marks visible on opened blaze.

A Fir 84" dia., bears S.35°W., 11 lks. dist., with scribe marks BT visible on opened blaze.

and trees marked by Byron

A Hemlock 15" dia., bears N.27°E., 65 lks. dist., with healed double blaze.

A Hemlock 13" dia., bears N.36°W., 38 lks. dist., with healed double blaze.

(Note: the trees mkd. by Byron, were not "recorded" in the typed 1957 field notes in the previous corner renewal system)
V.Laugen - April 1997)

continued next page

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2100, surveyed Sept. 2004 - (DCSO rec. Vol. 55 Page 21500) & 2008 BLM plat

The ¼ sec. cor. of secs. 17 & 18, monumented with on iron pipe. 1¼" dia. firmly set, projecting 15" above the ground, with brass cap mkd. as reported by Roseberry, et al, in 1969-73 from which the remains of the orig. BTs

A fir, 70" dia., bears S.60°E., 4.0 ft., with no marks visible on opened blaze.

A sawed fir stump, 77" dia., bears S.35°W.. 7.3 ft., with no marks visible on opened blaze.

and the remains of bearing trees reported by Roseberry. et al

A hemlock. 26" dia., bears N.27°E., 42.9 ft., with a healed blaze.

A sawed and decayed hemlock stump, 19" dia., bears N.36°W. 25.1 ft.. with no marks visible.

and a new bearing tree

A fir, 9" dia., bears N.87°W., 6.1 ft., mkd: ¼ S18 BT.