

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5812)

Set ¼ sec. post, from which
 An Oak 12" dia., bears N.14°W., 46 lks. dist.
 An Oak 12" dia., bears S.12°E., 164 lks. dist.

H.L. Eppstein, Co. Surveyor - Wit: W.S. Crear; H. Elpel; S. Manfred - March 24, 1925 - C.S. File 4/70

Set corner from old BTs which were badly rotten.
Marked new BTs:
 Red Fir 10" dia., bears N.42°W., (?) lks.
 Red Fir 6" dia., bears S.41°W., (?) lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - July/Aug. 1957 - C.S. File 49/5-17

Found both BTs and 1¼" Iron rod. See County Road survey notes renewed by Frear, in 1936.
 The 10" now 18" W.Fir checks for bearing and distance, S.60°E., 2.0 ft., shows good face. I do not open.
 The 50" R.Fir, East 13.0 ft., bark scribed ¼ S BT. I re-bark scribe this BT "¼S 29S 32 CS BT"
I can find no evidence of original BTs or Eppstein's BTs to support this corner. I do find BLM tags on trees at corner indicating it has been used as true corner.

Fd. and used, Dec. 1, 1989 by L. Roberts - M 109-38; C.S. File 63/102