

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5811)

Set ¼ sec. post, from which
A Fir 36" dia., bears N.75°E., 14 lks. dist.
A Fir 18" dia., bears S.25°W., 46 lks. dist.

Douglas Co. Surveyors Office - John M. Powell, and crew -
March 13, 1973 - C.S. File 56/25-27

Found - 36" D.Fir now 43", S.75°E., (Rec. N.75°E.) 9.2 ft.
Bark scribe faint but visible.
18" D.Fir now 31", S.25°W., 30.4 ft., bark scribe
visible ¼ BT.

Using two distances and 1 bearing, I SET brass cap at ¼ cor.
mkd. County Surveyors Office

T 28 S R 8 W

¼ $\frac{S\ 28}{S\ 33}$
1973

New BTs- 22" D.Fir S.74°W., 4.3 ft. scribed ¼ S33 CS BT.
14" W.Fir N.4°W., 15.7 ft. scribed ¼ S28 CS BT.

Fd. and used in BLM resurvey by James E. Jelley, Cadastral
Surveyor - under Group #863, surveyed May/July 1975 - (DCSO
records Vol. 38 Page(s) 15579)

Fd. OK, August 1993 by D. Bentz - M 117-61

Mark Smalley - For: Roseburg Resources - 2/2002 - M139-54

Found - 1973 county brass cap on iron pipe
BTs - 30" Fir S.25°W., 30.4' burned stump (OBT)
20" Fir S.76°W., 5.0' rotten stump
13" Fir N.3½°W., 15.2' down-rotten
Scribed- 9" Fir S.24°W., 27.7' "1/4 S BT"
9" Fir S.51°W., 25.3' "1/4 S BT"
14" Fir N.62°W., 25.1' "1/4 S BT"
12" Fir N.4°W., 21.2' "1/4 S BT"

Found OK by D. Edwards, Jan. 2003 - M141-66
FD. BC & 4 BTs, by K. Hoffine - 1/2009 - M158-54