

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page 5810)

Set post, cor. secs. 9, 10, 15 and 16, from which
An Ash 8" dia., bears N.16°E., 33 lks. dist.
A Fir 36" dia., bears N.69°W., 17 lks. dist.
A Cedar 15" dia., bears S.31°W., 16 lks. dist.
A Laurel 8" dia., bears S.13°E., 52 lks. dist.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15079)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T	28	S	R	8	W
		S	9	S	10
		S	16	S	15
					1969

from which

A Cedar 7" dia., bears N.58°E., 69 lks. dist. mkd. T28S R8W S10 BT.

A Fir 15" dia., bears S.45 3/4°E., 24 lks. dist. mkd. T28S R8W S15 BT.

A Fir 10" dia., bears S.10 1/4°W., 48 1/2 lks. dist. mkd. T28S R8W S16 BT.

A Fir 15" dia., bears N.26 1/2°W., 59 lks. dist. mkd. T28S R8W S9 BT.

Corner falls in wire fence extending N. and S. and at the SW. corner of a spring, seeps SW.

Fd. BC & 4 BTS B Shaner - 4/1972 - M42-66

BLM resurvey by Boyd W. Peterson, under Group #1364, Surveyed May/Aug. 1987 - (DCSO records Vol. 48 Page(s) 18404-05)

Point for the cor. of secs. 9, 10, 15 and 16, at proportionate distance.

From this point, the cor. reestablished by Roseberry, etal in 1969-73, bears S.64°31'W., 0.38 chs. dist. monumented with an iron post 2 1/2" dia., firmly set, projecting 4" above ground, with brass cap mkd. as described in the official record, from which the remains of the bearing trees mkd. in 1969-73

A root hole bears N.58°E., 69 lks. dist. with down Cedar alongside, 10 1/2" dia., with healed blaze.

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A Fir 18" dia., bears S.42°E., 24 lks. dist. with healed blaze. (Rec. S.45 3/4°E.)

A root hole bears S.13°W., 50 lks. dist. with down Fir alongside, 14" dia., with healed blaze. (Rec. S.10 1/4°W., 48 1/2 lks.)

A root hole bears N.12 1/2°W., 59 lks. dist. with down Fir alongside, 19" dia., with healed blaze. (Rec. N.26 1/2°W.)

Upon investigation of the area around this corner, it shows a large area slumping, which includes all of the bearing trees. The NE., NW., and SW. bearing trees have tipped over due to the movement of the ground, but have maintained proper position. Also, the record topography call of a wire fence extending N. and S. from the corner, is now East of the corner approx. 0.34 chs. dist.

Remove the iron post, destroy the marks on the bearing trees and at the true corner point

Reset the iron post, 28 ins. long, 2 1/2 ins diam., 24 ins. in the ground, with brass cap mkd.

T	28	S	R	8	W
	S	9		S	10
	S	16		S	15
				1969	

from which

A stainless steel post 28" long, 2 1/2" dia., set 26" in the ground for a reference monument, bears N.20°E., 150 lks. dist., with brass cap mkd. T28S R8W S10 RM and an arrow pointing to the corner.

A stainless steel post 28" long, 2 1/2" dia., set 28" in the ground for a reference monument, bears N.50°W., 150 lks. dist., with brass cap mkd. T28S R8W S9 RM, and an arrow pointing to the corner.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

David Edwards, for Roseburg Resources, Nov. 2003 - M143-25

Brass cap is missing, found both reference monuments OK