

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5821-22)

Set post 4 ft. long, 4" dia., 1 ft. in ground for ¼ sec. cor., from which
 A Hemlock 10" dia., bears S.75°E., 48 lks. dist.
 A Hemlock 18" dia., bears S.75°W., 33 lks. dist.

Arthur Boyer - Wit: Don Smith - July 1953 - C.S. File 41/176

Could not find old ¼ corner or any evidence of old witness trees. A random line was run from the NE. cor. of sec. 4 in a southerly direction and at a point 5217.0 ft. S. and 141.4 ft. E., the SE. cor. of sec. 4 was found. Thence North on a true line and

Set a 4" x 4" Fir post at 40 chains, for the ¼ corner - said corner being 40.4 chs. from the NE. corner of sec. 4, and 2595.0 ft. N. of the SE. corner of sec. 4., from which
 A 10" Hemlock, scribed "¼ S3 1581 BT", S.71°E., 20 ft.
 A 15" Fir scribed "¼ S4 1581 BT", located so that there is a smaller Fir between it and the corner.

This ¼ corner is in flat with no large trees, mostly small second growth firs and small hemlocks and not much underbrush, some rhododendron. There are many medium sized dead and badly decayed windfalls in this area. Blazed out line between 3 and 4.

Marvin C. Ramsey - For: Southern Oregon Plywood - July/Aug. 1962 - C.S. File 51/242

Established by Boyer, in 1953. Find Fir post, from which
 12" Hemlock bears S.71°E., 30 lks. mkd. ¼ S3 BT.
 17" Hemlock bears N.24½°W., 35 lks. mkd. ¼ S4 BT.
In place of the Fir post, SET an iron pipe 3 ft. long, 1½" dia., 28" in the ground, mkd. RS 404.

Survey by Richard Hintz - For: International Paper Co. - Dec. 1986 - M 103-8

Found - 1½" Iron pipe.
 14" Hemlock bears S.71°E., 19.8 ft. Tree down with healed blaze.
 18" Hemlock stump bears N.24°30'W., 23.1 ft., cut below blaze.
New BTs- 24" Hemlock bears S.36°E., 14.9 ft. scribed ¼ S3 BT
 14" Hemlock N.23°30'W., 17.5 ft. scribed ¼ S4 BT.