

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5816)</p> <p>-----</p> <p>Found it impossible to set the ¼ post on the precipitous and craggy mountain side.</p>
<p>BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15083)</p> <p>-----</p> <p>Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28" long, 2 1/2" dia., 12" in the ground, and in a mound of stone, 4 ft. base, to top, with brass cap mkd: T 28 S R 8 W ¼ $\frac{S 3}{S 10}$ 1969</p> <p>from which A Fir 12" dia., bears N.33°W., 15½ lks. dist. mkd. ¼ S3 BT. A Fir 43" dia., bears S.24½°W., 24½ lks. dist. mkd. ¼ S10 BT.</p>
<p>Fd. OK, March 1991 - M 111-70</p>
<p>Mark Smalley - For: Roseburg Forest Products - 11/5/96 - C.S. File 65/8-18</p> <p>-----</p> <p>Found - 1969 IPBC, BLM 21" Fir, N.33°W., 15.5 lks. 43" Fir, S.24¼°W., 24.5 lks.</p> <p>New BTs- 18" Fir, N.30°E., 24.5', scribed "¼ S BT" 9" Fir, S.39°W., 42.3', scribed "¼ S BT"</p>
<p style="text-align: right;">1</p>