

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 1

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Marvin C. Ramsey - For: J.H. Baxter and Co. - Filed Jan. 26, 1960 - C.S. File 51/65</p> <p>-----</p> <p>At intersection with the E. and W. center line. Set an Iron pipe 3 ft. long, 1½" dia., 28" in the ground mkd. RS 404, from which</p> <ul style="list-style-type: none">14" W.Fir bears N.16°E., 300 lks. mkd. C¼ S1 RS 404 BT.8" D.Fir bears S.83°E., 239 lks. mkd. C¼ S1 RS 404 BT.6" W.Fir bears S.77½°W., 182 lks. mkd. C¼ S1 Rs 404 BT.10" W.Fir bears N.42½°W., 277 lks. mkd. C¼ S1 RS 404 BT.
<p>Victor McLind - For: Edward A. Haynes - March 1975 - M 55-57</p> <p>-----</p> <p>Found Ramsey's 1½" pipe, leaning badly. I straighten and reset pipe from existing BTs as follows:</p> <ul style="list-style-type: none">A 14" W.Fir stump, bears N.16°E., 198.0 ft.A 8" D.Fir stump with scribe visible, bears S.83°E., 157.7 ft. <p>From this corner, a 1" I.P., no record, bears S.68°00'W., 28.13 ft.</p>
<p>Ronald G. Geisler - For: Champion International Corp. - Nov. 1985/Jan. 1986 - M 90-79</p> <p>-----</p> <p>Set an alum. cap on a 2½" x 30" alum. flared pipe in BPA R/W. Ramsey's 1960 I.P. bears S.00°57'15"E., 4.29 ft. from corner. New BTs-</p> <ul style="list-style-type: none">9" Fir bears N.45°W., 59.9 ft. scribed C¼ S1 BT.5" Fir bears N.19°E., 69.0 ft. scribed C¼ S1 BT. <p>An unrecorded 1" I.P. bears S.60°26'40"W., 29.92 ft. from corner.</p>
<p>Mark Heimburger - For: Right of Way Associates - Jan. 2005 - M147-7</p> <p>-----</p> <p>Found - 3/4" iron pipe w/2½" alum. cap. Corner is disturbed, reset per BTs.</p> <ul style="list-style-type: none">16" D.Fir with healed blaze bears N.46°W., 59.90'13" D.Fir with healed blaze bears N.19°E., 69.00' <p>New -</p> <ul style="list-style-type: none">5/8"x30" reinforcing rod with yellow plastic cap marked "LAND MARK" bears S.32°W., 42.90'.5/8"x30" reinforcing rod with yellow plastic cap marked "LAND MARK" bears S.61°W., 39.15'.