

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Sec. 36, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, Contract #57 dated April 12, 1855 (DCSO records, Vol. 14 Page 5792)

-----  
Set 1/4 sec. post, from which  
A Fir 24" dia., bears N.87°W., 32 lks. dist.  
A Laurel 12" dia., bears S.67°E., 28 lks. dist.

J.W. Cole, Co. Surveyor - Wit: W.H. Coats; E. Richardson; H. Bergh - Feb. 1923 - Vol. 3 Pg. 141-147; C.S. File 5/37; M 1-2

-----  
Set from orig. BTs. Laurel was nearly rotted away so I marked a new tree:  
An 18" Fir S.80½°E., 27.6 ft.  
Set Iron post 1" x 24" for corner, also Maple post 3"x3"x36"

GL0 resurvey by Mensch, 1924 (DCSO records, Vol. 14 Pages 5922-23)

-----  
Intersect the point for 1/4 sec. cor., located by record bearing & distance from the original NW bearing tree; marks are plain on the bark. The SE bearing tree is not found.  
At the exact cor. point:  
Set an iron post, 3' long, 1" dia., 28" in the ground, for 1/4 sec. cor. 36 only, with brass cap mkd:  
                  1/4  
                  S36 |  
                  1924  
from which (new bearing trees)  
A Fir, 16" dia. bears S.37°W., 42 lks. mkd: 1/4 S 36 BT.  
Original NW bearing tree,  
A Fir, 36" dia., N.87°W., 32 lks. mkd: S BT.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - April 1961 - C.S. File 49/50-47

-----  
Found - 1" I.P. at corner.  
Orig. 24" now 36" Fir stump, N.87°W., 21.1 ft. We open near base and find good scribing "BT".  
Brass cap not found and no other BTs of record fd.  
Set Brass cap at cor. and under 4 ft. log mkd: County Surveyor's Office, 1961 E 1/4 S36 T28S R8W.  
New BT - 12" R.Fir bears S.41°E., 54.8 ft. scribed 1/4 S36 CS BT.  
No other trees near.

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION E. ¼ Cor. Sec. 36 only, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Doug. County Surveyors Office - S.J. Flause; R.W. Smith  
June 10, 1987 - C.S. File 62/45-12

-----  
Found - 1½" dia. 1961 DCS0 brass cap, properly mkd., on a 1"  
I.D. iron pipe, firmly set, & protruding 16"  
above ground.  
1" dia. Iron pipe from Cole, not evident.  
From orig. 1855 Hathorn survey, a 24" Fir dia., now  
a 36" dia. 3 ft. tall Fir stump with the scribing  
"BT" visible in an opened blaze, bears N.87°W.,  
21.2 ft. (as per rec.)  
24" B.Oak searched for and not found.  
SE 16" Fir not searched for.  
From 1924 resurvey, no evidence of SW BT found.  
12" R.Fir now a 12" dia. 2 ft. tall Fir stump with  
rotted blaze on fallen trunk, no scribing found,  
bears S.41°E., 54.8 ft. as per rec. (Byron)  
Monument position is perpetuated as found.  
New BTs - 11" D.B.H. D.Fir scribed "¼ S36 CS BT" on a double  
blaze bears N.74½°W., 40.2 ft.  
10" D.B.H. W.Fir scribed "¼ S36 CS BT" on a double  
blaze bears S.49½°W., 22.9 ft.  
Monument lies in break of steep easterly slope approx. 100  
ft. ± , S.09°W., from N-S switch back in private road.