

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Cadastral Engineer, Group No. 62, dated Dec. 21, 1920 - (DCSO records Vol. 25 Page 10674)

Set an iron post, 3 ft. long, 2" dia., 26" in the ground, for cor. of secs. 5, 6, 7, & 8, with brass cap mkd

T29S R1E
S 6 | S 5
S 7 | S 8
1921

from which

- A fir, 12" dia., bears N.53°E., 42 lks mkd: T29S R1E S5 BT
- A hemlock, 7" dia., bears S.55°E., 3 lks., mkd: T29S R1E S8 BT.
- A yew, 14" dia., bears S.2°W., 21 lks. mkd: T29S R1E S7 BT
- A hemlock, 24" dia., bears N.82°W., 66 lks., mkd: T29S R1E S6 BT.

Douglas Co. Surveyors Office - Gary Langlitz - Peter Earle - Aug. 29, 1974 - C.S. File 57/2-17

Found - An orig. 24" Hemlock, now a 26" stump, rotten. We open and find good scribing "29S R1E S6 BT".
There is no trace of the three remaining orig. BTs or the orig. corner monument.

At the true cor. point as determined from the only remaining orig. BT, a 26" Hemlock stump, bearing N.82°W., 43.6 ft., we

Set - A Brass Cap mkd: COUNTY SURVEYORS T 29 S
OFFICE S 6 | S 5
S 7 | S 8
1974 R 1 E

New BTs - 6" G.Fir, bears N.66°E., 35.6 ft. scribed "T29S R1E S5 CS BT"

5" G.Fir, bears S.23°E., 44.9 ft. scribed "S8 CS BT"

There are no other suitable trees in the vicinity.

This corner lies at the bottom of the cutbank and along the westerly edge of an abandoned logging road. It is also situated in a old logging unit.