

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Cadastral Engineer, Group No. 62, dated Dec. 21, 1920 - (DCSO records Vol. 25 Page 10662)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for
¼ sec. cor., with brass cap marked

¼
S 8|S 9
1921

from which

A fir, 10" dia., bears S.41°E., 26 lks., mkd: ¼ S9 BT.

A fir, 48" dia., bears S.81°W., 7 lks., mkd: ¼ S8 BT.

Cor. No. 30 HES No. 143, which is porphyry stone, 10x16x12" above ground, firmly set, marked and witnessed as described in field notes of HES No. 143, bears N.10°26'E., 13.98 chs.

U.S. Forest Service, Tiller Ranger District - (Filed Nov. 16, 1973) - C.S. File 56/40-50

Found - Brass cap

No information on BTs

Note - Best route to reach cor. Use FS Rd No. 2826.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Debbie Stewart & Janet Lundeen - May 13, 1981 - C.S. File 61/24-19

Found - GLO Brass Cap stamped:

¼
S 8|S 9
1921

firmly set 10" above the ground.

A 48" now 48" Fir stump with well healed blaze bears S.82°W., 5.2 ft.

A 10" now 12" fir with partially healed blaze showing "¼ S9 BT" bears S.60°E., 16.3 ft.

Orig. 10" Fir, down & rotted. Stump hole bears S.38°E., 17.0 ft. No face or scar visible on tree. Tree is now 15" dia.

New BTs- 14" Fir bears S.75°W., 30.9 ft. scribed "¼ S8 CS BT" in double blaze.

All BTs have DCSO BT tags.