

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION ¼ Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Cadastral Engineer, Group No. 62, dated Dec. 21, 1920 - (DCSO records Vol. 25 Page 10661)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ sec. cor., with brass cap marked

¼ $\frac{S \ 9}{S \ 16}$
1921

from which

A fir, 8" dia., bears N.30°W., 3 lks., mkd: ¼ S9 BT.

A fir, 18" dia., bears S.72°W., 18 lks., mkd: ¼ S16 BT.

U.S. Forest Service, Tiller Ranger District - 6/18/1959 -
(Filed Nov. 16, 1973) - C.S. File 56/40-77

Found - Brass cap

No information on BTs

Note - Best route to reach cor. use FS Rd. No. 284, 2826 or 272W

Douglas Co. Surveyors Office - Gregory Quibell, Deputy -
Terrie Plouff & Teresa Buley - 10/12/1981 - C.S. File 61/27-8

Found - Orig. 1921 Brass Cap firmly set, protruding 10" out of the ground, marked: ¼ S9 S16 1921

Orig. 18", now 25" Fir with well healed scar bears S.72°W., 12.3 ft

Orig. 8" Fir 3 lks from corner is completely gone.

New BTs- 13" Fir bears N.18°W., 51.7 ft., scribed ¼ S9 CS BT in dbl blaze.

13" Fir bears N.21°E., 27.8 ft., scribed ¼ S9 CS BT in dbl blaze.

13" Fir bears S.80°E., 12.8 ft., scribed ¼ S16 CS BT in dbl blaze

Note - Corner is S.20°W, 75 ft of old dirt logging road.