

PRIMARY CORNER DESCRIPTION Cor. No. 10 HES 143

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12018)

-----

Cor. No. 10, identical with Cor. H/16 of listing survey No. 6-97, a post, mkd. and witnessed as described by the listing surveyor, in place of which I set a porphyry stone, 24x10x7", 14" in the ground, for Cor. No. 10, mkd. 10 HES 143 on E face, with a cross (+) on top; from which

A fir, 16" dia., bears S.0°50'W., 60 lks.  
A fir, 16" dia., bears N.6°20'E., 35 lks.  
both trees blazed and scribed 10 HES 143 BT.  
Pits & mound impracticable at this and all other cors..

---

Looked for/not fd. DCSO VRT 12/1969 - C.S. 54/82-92: No trace due to road way & land clearing.

---

Maurice E. Farr, USFS - July 1975 - M56-26

-----

Set - 1"x36" galv. pipe with Brass cap stamped "T29S HES 143 COR. 10 PE 5188 R1E 1975" from which bears:

A 22" cedar S.47°30'W., 103.8', scribed 10 HES 143 BT.  
A 16" cedar S.86°30'W., 217.3', scribed 10 HES 143 BT.

---

Douglas Co. Surveyors Office - Gary Langlitz - Frank Silage - March 19, 1979 - C.S. File 64/50-20

-----

Referenced notes only

Found - Corner location falls in roadway; no trace of orig. monument or accessories.

Brass cap, buried 6", marked T29S R1E HES 143 Cor. 10 1975 PE 5188.

22" now 25" I.Cedar with scribing "10 HES 143 BT" visible on a single unhealed blaze bears S.47½°W., 103.8 ft.

16" now 17" I.Cedar with scribing "10 HES 143 BT" visible on a single unhealed blaze bears S.86½°W., 217.3 ft.

Reconstruction of the road way may disturb this corner. We reference its location as follows:

Directly beneath the scribed "BT" on each of the previously described BTs we drive a "PK" masonry nail for use as a sight.

On line between the corner point and the PK nail on each BT, we set:

A 5/8"x30" I.Rod with alum. cap bears S.86½°W. 123.46 ft  
A 5/8"x30" I.Rod with alum. cap bears S.47½°W., 37.81 ft.

CONT

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 943100

PRIMARY CORNER DESCRIPTION Cor. No. 10 HES 143

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 11/10/93 C.S. File 64/50  
-----

Found - 2½" dia, brass cap along easterly shoulder of gravel road, 12" below ground.  
22" now 32" dia., I.Cedar with a fully healed single blaze, bears S.45½°W., 103.8' (Rec. S.47½°W., 103.8') (1975) PK nail set in blaze as sight in 1979 is healed over.  
16" now 19" dia., I.Cedar with a partially healed single blaze scribing visible "10 HES 143 BT" and PK nail set in blaze. BT bears S.84½°W., 217.3'. (Rec. S.86½°W., 217.3') 1975  
5/8" I.R. with Alum. DCSO cap stamped "BO2 10", bears S.84½°W., 123.46' (Rec. S.86½°W., 123.46') 1979. Alum. locator post along side.  
5/8" I.R. with Alum. DCSO cap stamped "BO1 10", bears S.45½°W., 37.8' (Rec. S.47½°W., 37.81') 1975. Alum. locator post along side.  
New BT - 8" D.Fir double blazed and scribed "10 HES 143 CS BT", bears North, 62.9'.  
See sketch in file.