

PRIMARY CORNER DESCRIPTION Cor. No. 11 HES 143

| Alias | Description |
|-------|-------------|
| | |
| | |
| | |
| | |

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12019

Cor. No. 11, identical with Cor. H/17 of listing survey No. 6-97, a post, mkd. and witnessed as described by the listing surveyor. I remove tree, in place of which I set a porphyry stone, 24x10x10" 14" in the ground, for Cor. No. 11, mkd. 11 HES 143 on SE face, with a cross (+) on top; from which

- A fir, 14" dia., bears S.56°30'W., 20 lks.
- A fir, 20" dia., bears N.61°40'W., 24 lks.

both trees blazed and scribed 11 HES 143 BT.
Pits & mound impracticable at this and all other cors.

Looked for/not fd. DCSO VRT 12/1969 - C.S. 54/82-92: No trace due to road way & land clearing.

Maurice E. Farr, USFS - July 1975 - M56-26

Set - 1"x36" galv. pipe with Brass cap stamped "T29S HES 143 COR. 11 PE 5188 R1E 1975" from which bears:

- A 8" hemlock N.71°45'W., 33.3 ft scribed 11 HES 143 BT.
- A 6" fir N.29°W., 42.5 ft. scribed 11 HES 143 BT.

Leonard Herzstein, USFS & Deputy Co. Surveyor - Witnesses: J. Landrum & T. Wolford - April 1981 - C.S. File 61/19-24

Found - 1" IP firmly set, 10" below surface of USFS Rd. #2826, with brass cap properly marked. Corner lies under east edge of road.

- 6" Hemlock, N.71°45'W., 33.3 ft. with scribe marks "11 HES 143 BT" visible on partly healed blaze.
- A root hole N.29°00'W., 42.5 ft. with 6" W.Fir log alongside with scribe marks "11 HES 143 BT" visible on partly healed blaze.
- A RM set by USFS in 1975, a 4"x4" wood post bears East 5.0 ft (to face) with location tag attached.

New BT - A 9" D.Fir N.33½°W., 41.8 ft. marked "11 HES 143 CS BT" on double blaze.

1